

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
South Lakewood Com.	
9. Well No.	
1 1-Y	
10. Field and Pool, or Wildcat	
Wildcat, Morrow	
12. County	
Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS DEC 9 1976
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER- Dry Hole
2. Name of Operator		
Llano, Inc.		
3. Address of Operator		
P. O. Box 1320, Hobbs, New Mexico 88240		
4. Location of Well		
UNIT LETTER E 1980 FEET FROM THE North LINE AND 840 FEET FROM THE west LINE, SECTION 3 TOWNSHIP 20-S RANGE 26-E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		
3259 GL		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned as follows:

11-2-76 Set 40 sx plug from TD to 10,140'
Set 40 sx plug from 9,400' to 9,500'
Set 40 sx plug from 7,900' to 8,000'
Set 40 sx plug from 7,250' to 7,350'
Set 40 sx plug from 5,500' to 5,600'
Set 40 sx plug from 3,000' to 3,100'
set 40 sx plug from 2,000 to 2,100'
Heavy mud placed between plugs

11-5-76 RIH w/tbg & pkr. Acidized open hole interval 1,900' to 2,000' w/2,000 gals BDA acid. Swabbed well. Rec 59 to 55 BWP, no show of oil.

11-8-76 POH w/tbg & pkr. set 50 sx cmt plug from 1,850' to 1,950'. Set 50 sx cmt plug from 900' to 1,000'. Set 15 sx cmt plug from 35' to surf. Placed heavy mud between plugs. Installed 4' dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Manager of Operations
and Construction

SIGNED [Signature] TITLE Manager of Operations and Construction DATE 12-6-76

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: