UI ED STATES (ormerly 9=301) DEPARTMENT OF THE INTE BUREAU OF LAND MANAGEME		Form approved. Budget Burgau No. 1004-013-AC Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL N. NM 18605
SUNDRY NOTICES AND REPORTS	S ON WELLS ug back to a different reservoir.	6 IF INDIAN. ALLOTTEE OR TRIBE NAME
11 ²	KELLINEV	7. UNIT AGBEEMENT NAME
A ELL WELL AA OTHER		8. FARM OR LEASE NAME
Enron Oil & Gas Company		Federal RV 4
P. O. Box 2267, Midland, Texas 79702	AND THE OFFICE F	9. WBLL NO.
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT
		Revelation Morrow
		11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA
1980' FEL & 660' FSL		Sec 4, T22S, R25E
30 015 21981 15 ELEVATIONS (Show whether 3600' GR	DF, RT, GR. etc.)	12. COUNTY OF PARISH 13. STATE
		Eddy NM
Check Appropriate Box To Indicate	Nature of Notice, Report, or (Other Data
NOTICE OF INTENTION TO :	S UBSEQ	UENT REPORT OF: 12/3/91
TEST WATER SHUT-OFF PULL OR ALTER CONSING EBACTURE TREAT NULLIPLE COMPLETE	WATER SHUT-OFF	BEPAIRING WELL
SHOOT OR ACIDIZE ABANDON®	FBACTUBE TREATMENT	ALTEBING CASING
ELPAIR WELL CHANGE PLANS (Dther)	Other)	ABANDONMENT* X
Released Otis Permalatch packer and TOP Set CIBP at 8550'; set cement to 8510' Cut 5-1/2" casing at 5000' & LD 123 jo Mixed 65 sack cement pump plug from 50	ints 17# N-80 casing.	
Mixed 65 sack cement pump plug from 50		
Spot 50 sack plug from 2370' to 2270'.		\sim / \sim
Spot 50 sack plug from 2370' to 2270'. Spot 25 sack plug from 260' to 360'.		\sim / \sim
Spot 25 sack plug from 260' to 360'.	- Tagged plug at 2280 dry-hole marker.	D'. Post ID-2 2-5-93 PortA
Spot 25 sack plug from 260' to 360'. Spot 25 sack plug 50' to surface. Rig released 1-13-93. P&A. Installed Approved as to plugg Liability under bond surface restoration is	- Tagged plug at 2280 dry-hole marker.	2 $($
Spot 25 sack plug from 260' to 360'. Spot 25 sack plug 50' to surface. Rig released 1-13-93. P&A. Installed Approved as to pluge Liability under bond surface restoration is I hereby certion that the foregoing is true and correct	- Tagged plug at 2280 dry-hole marker.	D'. Post ID-2 2-5-93 PortA NAMAGENERIT

*See Instructions on Reverse Side