

Directions to W.B. Barnhill No.1 Brainerd Federal

Location: 660' FNL & 1980' FEL, Sec.1 T-22-S, R-21-E, Eddy Co. NM

Take Hwy 285 South from Artesia to 7-Rivers, turn west .3 mi south of 7-Rivers on blacktop going west & southwest to the Marathon Gas Plant.

At stop sign at intersection with Marathon plant road turn west on blacktop.

2.2 miles Marathon Gas plant on south side of road.

Go past Marathon gas plant 5.7 miles to road junction, take right hand calichie road at old car body.

0.1 miles cattle guard

1.9 miles road to north to Great Western dry hole, stay on west bound road.

1.4 miles turn left, south, at Great Western sign follow main traveled road.

1.4 miles cattle guard, El Paso sign, straight ahead on main traveled road

3.3 miles bear right towards tank batteries.

0.5 miles Calichie pit on right, tank battery on left.

0.7 miles cattle guard

0.6 miles road forks, turn right towards windmill.

0.7 miles Location, Continental No.1 East Texas Hills dry hole, Calichie pit, wind mill. Continue north.

0.7 miles flag stake-location 265 feet east.