

N.M.O.C.D. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-N1121

8. LEASE DESIGNATION AND SERIAL NO.

NM-15670

9. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

Gulf Oil Corporation /

3. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1680' FNL & 1980' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cardenas Federal Com

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Wildcat
Bone Springs

11. SEC., T., R., M., OR BEK. AND
SURVEY OR AREA

Sec 29-20S-28E

12. PERMIT NO.

13. ELEVATIONS (Show whether DF, ET, CR, etc.)

3228' GL

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

P&A

☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting for
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

Circulate abandonment mud 5800'-4870'. Set CIBP at 5690', cap with 35' cement. Cut casing at approx 4870' or by free point calculation. Spot 50' cement inside casing stub at cut-off point and 50' above. Circulate abandonment mud to surface. Spot 100' cement plug 3800'-3700'. Spot 50' cement below 8-5/8" casing shoe and 50' above to 2850'. Spot 10 sack surface plug. Place dry hole marker, clean and clear location.

Plug depth as per George Stewart - USGS, Roswell.

RECEIVED

FEB 06 1981

O. C. D.
ARTESIA, NEW MEXICO

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED R. D. Pritch

TITLE Area Engineer

DATE 1-14-81

(This space for Federal or State office use)

APPROVED BY George H. Stewart

ACTING DISTRICT ENGINEER

DATE FEB 06 1981

CONDITIONS OF APPROVAL, IF ANY: