

RECEIVED

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

MAY 13 1982
NEW MEXICO OIL CONSERVATION COMMISSION

O.C.D.
ARTSIA OFFICE

c/mms

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L - 5129	
7. Unit Agreement Name	
8. Farm or Lease Name Marathon - State	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat wellcamp	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

1. Name of Operator
Mewborne Oil Company ✓

2. Address of Operator
P. O. Box 7698 Tyler, Texas 75711

3. Location of Well

UNIT LETTER A 660 FEET FROM THE North LINE AND 1315 FEET FROM
THE East LINE, SECTION 30 TOWNSHIP 20S RANGE 27 E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3221 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-30-82 Set C.I.B.P. at 7880' and cap it with 25 sacks of cement.
- Mixed mud and circulate hole with 10# salt gel mud.
- 5-3-82 Spotted a 35 sack plug in and out of 4½" casing stub at 5994'. W.O.C. and tagged at 5820'.
- 5-3-82 P.U.H. with tubing 5562' and spot a 35 sack plug.
- 5-3-82 P.U.H. with tubing to 3059' and spot a 35 sack plug.
- 5-3-82 P.U.H. with tubing 2008' and spot a 35 sack plug. W.O.C. Tagged at 1802' across 8 5/8 shoe.
- 5-4-82 P.U.H. to 556' and spot a 35 sack plug. P.O.H.
- Cut off well head and place a 10 sack surface plug and dry hole marker.

Posted ID 2
5-21-82
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Delora Heard TITLE Production Clerk DATE 5-6-82

APPROVED BY [Signature] TITLE Genl Rep DATE 2/20/96

CONDITIONS OF APPROVAL, IF ANY: