## State of New Mexico Energy, ...nerals and Natural Resources Department

F	o	m	1	c.	-1	0	3	
R	e	vi	SF	м	1	-1	۱-8	q

DISTRICT I 1625 N. French, Hobbs, NM 88240

HL	COL	NSE	KΛ	$\mathbf{AI}$	ION	DI	/151
		_	_	_			

WELL API NO. 3001523443		
F Indiana Tomo of I	0000	

DISTRICT II	P.O	Box 2088			3001323443	•	
811 South First, Artesia NM 88210	Santa Fe, New 1	Mexico 87	504-2088		5. Indicate Type o	f Lease	
DISTRICT III	•					STATE 🏻	FEE 🗌
1000 Rio Brazos Rd., Aztec, NM 87410					6. State Oil & Gas	Lease No.	
					L-4861		
SUNDRY NOTI (DO NOT USE THIS FORM FOR PRO	CES AND REPORT			Z TO 4			
<b>(</b> — · ·	OIR. USE "APPLICATI			X IO A	7. Lease Name or	Unit Agreement Na	ıme
(FORM C		Avalon (Delaware) Unit					
1. Type of Well:							
l Gii G	gas Vell D Other						
	Vell U Other	r					
2. Name of Operator					8. Well No.		
Exxon Corp.					433		
3. Address of Operator P. O. Box 435	58				9. Pool name or W	Vildcat	
Houston, 7	Геха <mark>s 77210-435</mark> 8				Avalon Delaw	are 3715	
4. Well Location		-					
Unit Letter I : 2180	Feet From The	South	Line and	660	_ Feet From The	East	Line
Section 36	Township $20\mathrm{S}$		Range 27E	N	NMPH	E	ddy County
	10. Elevation (Sh	ow whether.	DF, RKB, RT, GR	, etc.)	3309 GR		
	<u> </u>						<del></del>

Sec		: <u>2180</u> i	Feet From The	South	Line and	<u>660</u> F	et From The	<u> East</u> Line	
$\overline{\tau\tau\tau\tau\tau\tau}$	ction 36		Township 20S		Range 27E	NMF	Н	Eddy Cou	nty
			10. Elevation (.	Show whether	DF, RKB, RT, GR	, etc.)	3309 GR		
1.	Check NOTICE O		riate Box to Ir TION TO:	ndicate Na	ature of Noti	_	or Other I JENT REF		
PERFORM :	REMEDIAL WOR	K 🗆 PLU	JG AND ABAND	on 🗆	REMEDIAL V	WORK	$\boxtimes$	ALTERING CASING	
<b>FEMP</b> ORAI	RILY ABANDON	☐ CH.	ANGE PLANS		COMMENCE	DRILLING (	DPNS.	PLUG & ABANDONME	νт [
PULL OR A	LTER CASING				CASING TES	T AND CEMI	ENT JOB 🔲		
OTHER:					OTHER:				
work) SEE 1-18-99 1-19-99 1-20-99 1-21-99	MIRU. Tag ( Drill out cmi Pump 1500 g Frac 46-4630 Tag sand @ 4 Install 2x1 1	Cmnt @ 6 1t and CI (al of 7 1/ 2 w33,750 4616, clea	4590'. IBP @ 4650; I 2% HCL, 6 I gal of HES I an out to 4659	Perf 4600 BPM @ 1 Hybore F	0-4630 w/2 S 1900 psi, ISI	PF (60 sho P - 33 psi.	ots).	starting any proposed	