				$\cap$
Form 3160–5 (JUNE 1990)	DEPARTMEN	ED STATES IT OF THE INTERIOR LAND MANAGEMENT	811 S 1st Street	ivisiQterm APPROVED Budget Bureau No. 1004–0135 2834 Expires: March 31, 1993 5. Lease Designation and Serial No.
Do not use this form fo	or proposals to dr	AND REPORTS ON WE ill or to deepen or reentry test DR PERMIT-" for such proper	ELLS	NM-17103 6. If Indian, Allottee or Tribe Name
1. Type of Well		IT IN TRIPI ICATE	1 8 1996	7. If Unit or CA, Agreement Designation NM061P35-84C445
Oil Gas           Oil         Gas           Well         X         Well         Other           Name of Operator         X         X         X         X	STRATA PRO			8. Well Name and No. Lee Federal Com #2 9. API Well No.
3. Address and Telephone No.	P.O. Box 103		505-622-1127	30-015-24349 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec.	, T., R., M., or Survey 1980' FNL & Section 25–2	1980' FEL	Burton Flat Atoka (Gas) 11. County or Parish, State Eddy County, New Mexico	
12. CHECK APPROF TYPE OF SUBMISS		TO INDICATE NATURE	OF NOTICE, REPOR TYPE OF ACTION	T, OR OTHER DATA
[X]       Notice of Intent         []       Subsequent Report         []       Final Abandonment	Notice	Abandonment X Recompletion X Plugging Back Casing Repair Altering Casing OTHER		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.
				imated date of starting any proposed work. s pertinent to this work.)* aware formation as set out

11

1

- 1. MIRU completion unit. ND wellhead. NU BOP. Unseat packers. TOH with 2 3/8" tubing.
- 2. Set CIBP at 11275'. Dump 35' of cement on top. Set CIBP at 10700'. Dump 35' of cement on top.
- 3. Set 100' cement plug at 8994' with 25 sacks Class "H" cement.
- 4. Set 100' cement plug at 5518' with 25 sacks Class "H" cement.
- 5. Cut casing at free point. Pull and lay down 7" casing. Set 100' cement plug with 50 sacks Class "H" cement half in and half out of casing stub.
- 6. Run RST log from 3300' to 3000'. Evaluate.

below:

- 7. Perforate 8.42 holes from 3123'-3130'. Acidize with 1500 gallons 7 1/2% NEFE acid. Flow back and swab test.
- 8. TOH with tools. TIH with production string. Place well on production.

	0	·		Pth
14. I hereby certify that the foregoing is true and correct Signed (certal Anarcia	Title	Production Records Manager	Date	11/11/96
(This space for Federal or State office use) Approved <b>VORIG. SGD.) ALEXIS C. SWOBODA</b> Conditions of approval, if any:	Title	PETROLEUM ENGINEER	Date	11/14/96
				·

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.