Dec. 1973				Budget Bureau N	
000. 1979	UNIFED STATES THE COM	िद्धा	ONASE		
	DEPARTMENT OF THE INTERIOR		LC-060572-A	A .	
	GEOLOGICAL SURVEY	1) 6.	IF INDIAN, ALLO	TTEE OR TRIBI	E NAME
SUNDR	Y NOTICES AND REPORTS ON WELLS	7.	UNIT AGREEME		<u> </u>
(Do not use this	form for proposals to drill or to deepen or plug back to a different or 9-331-C for such proposals.		Big Eddy Ur FARM OR LEASE		······································
1. oil 😿	gas		Big Eddy	NAME ,	
	well other F OPERATOR Image: Constraint of the second sec	- 9.	WELL NO. 100		
	F OPERATOR Petroleum, Inc.	10	FIELD OR WILDO	TAT NAME	
	OF OPERATOR	-	Undesignate		Spring
Box 10		+	SEC., T., R., M., AREA		
4. LUCATION below.)	N OF WELL (REPORT EOCATION CLEARLY, See space 17		Sec. 8, T2	lS, R28E	
AT SURF	ACE:2291' FSL & 483' FWL NW/4 NW/4 Unit 1	L 12.	COUNTY OR PAI		TE
	PROD. INTERVAL: same		Eddy	NM	
	L DEPTH: same		API NO.		
	OR OTHER DATA		ELEVATIONS (S 3178.0 GR	HOW DF, KDE	3, AND W
REQUEST FO	R APPROVAL TO: SUBSEQUENT REPORT OF:	L	<u>9170.0 GR</u>		
TEST WATER			• .	-	
FRACTURE T SHOOT OR A					
REPAIR WELI		(N(OTE: Report results	of multiple com	pletion or zo
PULL OR AL	TER CASING	(N)	OTE: Report results change on Fo		pletion or zo
PULL OR AL MULTIPLE CO	TER CASING	(N)			pletion or ze
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON*	TER CASING	(14)			pletion or zo
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON*	TER CASING	(N(pletion or zo
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE	TER CASING	ite all p directic	change on Fo pertinent details, nally drilled, giv	rm 9–330.)	tinent dat
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84	TER CASING DMPLETE NES emeral Drilling Operations BE PROPOSED OR COMPLETED OPERATIONS (Clearly states) gestimated date of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine Spud @ 2:00 pm 4/3/84.	ite all p directio ent to th	change on Fo pertinent details, phally drilled, giv his work.)*	rm 9–330.) , and give per e subsurface to	tinent dat ocations a
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84	TER CASING DMPLETE NES eneral Drilling Operations BE PROPOSED OR COMPLETED OPERATIONS (Clearly sta g estimated date of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine	te all p directic ent to th $17\frac{1}{2}$ "	change on Fo pertinent details, onally drilled, giv his work.)* hole. Cmt	rm 9–330.) , and give perf e subsurface k w/400 sx ''	tinent dat ocations a 'C''
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84	TER CASING DMPLETE NES Eneral Drilling Operations SE PROPOSED OR COMPLETED OPERATIONS (Clearly states) g estimated date of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine Spud @ 2:00 pm 4/3/84. Run 9 jts 13 3/8" 54.5#, @ 341' 1	te all p directic ent to th $17\frac{1}{2}$ "	change on Fo pertinent details, onally drilled, giv his work.)* hole. Cmt	rm 9–330.) , and give perf e subsurface k w/400 sx ''	tinent dat ocations a 'C''
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84	TER CASING DMPLETE NES SE PROPOSED OR COMPLETED OPERATIONS (Clearly states of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertines Spud @ 2:00 pm 4/3/84. Run 9 jts 13 3/8" 54.5#, © 341 1 + 2% CaCl. Circ 50 sx. WOC 18 hrs.	ite all p directic ent to th BLM m 2#, 2 50 sx	change on Fo pertinent details, onally drilled, giv his work.)* hole. Cmt witness: P 8# & 24# 8 "C" + 1% C	rm 9-330.) , and give perf e subsurface k w/400 sx " ete Hines 5/8" J-55 aCl. Circ	tinent dat ocations a 'C'' ST&C - 250
PULL OR AL MULTIPLE CC CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84	TER CASING DMPLETE NES meral Drilling Operations BE PROPOSED OR COMPLETED OPERATIONS (Clearly sta g estimated date of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine Spud @ 2:00 pm 4/3/84. Run 9 jts 13 3/8" 54.5#, © 34.1 1 + 2% CaCl. Circ 50 sx. WOC 18 hrs. Test casing to 800# for 30 min. OK Drill 11" hole to 2579'. Run 64 jts 32 Land @ 2579'. Cmt w/1500 sx light, 15 sx cmt. BLM witness: Burt Jones. WOC OK.	tte all p directic ent to th BLM m 2#, 2 50 sx DC 18	change on Fo pertinent details, onally drilled, giv his work.)* hole. Cmt witness: P 8# & 24# 8 "C" + 1% C hrs. Test	rm 9-330.) , and give perf e subsurface k w/400 sx " ete Hines 5/8" J-55 aCl. Circ	tinent dat ocations a 'C'' ST&C : 250
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84 4/5/84 4/8/84	TER CASING DMPLETE NES meral Drilling Operations BE PROPOSED OR COMPLETED OPERATIONS (Clearly states and the of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine Spud @ 2:00 pm 4/3/84. Run 9 jts 13 3/8" 54.5#, @ 34.1 1 + 2% CaCl. Circ 50 sx. WOC 18 hrs. Test casing to 800# for 30 min. OK Drill 11" hole to 2579'. Run 64 jts 32 Land @ 2579'. Cmt w/1500 sx light, 15 sx cmt. BLM witness: Burt Jones. WOC OK. Reach TD @ 12:45 am MST. POH, prep to	tte all p directic ent to th BLM v 2#, 2 50 sx 50 sx 50 sx 50 sx	change on Fo pertinent details, phally drilled, giv his work.)* hole. Cmt v witness: P 8# & 24# 8 "C" + 1% C hrs. Test well.	rm 9-330.) , and give perfected e subsurface to w/400 sx '' ete Hines 5/8'' J-55 aCl. Circ casing to	tinent dat ocations a 'C'' ST&C 250 1000#
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84 4/5/84 4/8/84	TER CASING DMPLETE NES meral Drilling Operations BE PROPOSED OR COMPLETED OPERATIONS (Clearly states and the of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine Spud @ 2:00 pm 4/3/84. Run 9 jts 13 3/8" 54.5#, @ 34.1 1 + 2% CaCl. Circ 50 sx. WOC 18 hrs. Test casing to 800# for 30 min. OK Drill 11" hole to 2579'. Run 64 jts 32 Land @ 2579'. Cmt w/1500 sx light, 15 sx cmt. BLM witness: Burt Jones. WOC OK. Reach TD @ 12:45 am MST. POH, prep to	tte all p directic ent to th BLM v 2#, 2 50 sx 50 sx 50 sx 50 sx	change on Fo pertinent details, phally drilled, giv his work.)* hole. Cmt v witness: P 8# & 24# 8 "C" + 1% C hrs. Test well.	rm 9-330.) , and give perfected e subsurface to w/400 sx '' ete Hines 5/8'' J-55 aCl. Circ casing to	tinent dat ocations a 'C'' ST&C : 250 > 1000#
PULL OR AL MULTIPLE CO CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84 4/5/84 4/8/84 4/23/84 Subsurface S	TER CASING DMPLETE NES meral Drilling Operations BE PROPOSED OR COMPLETED OPERATIONS (Clearly sta g estimated date of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine Spud @ 2:00 pm 4/3/84. Run 9 jts 13 3/8" 54.5#, © 34.1 1 + 2% CaCl. Circ 50 sx. WOC 18 hrs. Test casing to 800# for 30 min. OK Drill 11" hole to 2579'. Run 64 jts 32 Land @ 2579'. Cmt w/1500 sx light, 15 sx cmt. BLM witness: Burt Jones. WOC OK.	tte all p directic ent to th BLM v 2#, 2 50 sx 50 sx 50 sx 50 sx	change on Fo pertinent details, phally drilled, giv his work.)* hole. Cmt v witness: P 8# & 24# 8 "C" + 1% C hrs. Test well.	rm 9-330.) , and give perfected e subsurface to w/400 sx '' ete Hines 5/8'' J-55 aCl. Circ casing to	tinent dat ocations a 'C'' ST&C : 250 > 1000#
PULL OR AL MULTIPLE CC CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84 4/5/84 4/8/84 4/23/84 Subsurface S 18. 1 hereby	TER CASING DMPLETE NES meral Drilling Operations SE PROPOSED OR COMPLETED OPERATIONS (Clearly states of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine Spud @ 2:00 pm 4/3/84. Run 9 jts 13 3/8" 54.5#, @ 341 1 + 2% CaCl. Circ 50 sx. WOC 18 hrs. Test casing to 800# for 30 min. OK Drill 11" hole to 2579'. Run 64 jts 32 Land @ 2579'. Cmt w/1500 sx light, 15 sx cmt. BLM witness: Burt Jones. WO OK. Reach TD @ 12:45 am MST. POH, prep to Safety Valve: Manu. and Type	the all p directic ent to the $L7\frac{1}{2}$ " 1 BLM m 2#, 2 50 sx DC 18 co log	change on Fo pertinent details, onally drilled, giv his work.)* hole. Cmt witness: P 8# & 24# 8 "C" + 1% C hrs. Test well.	rm 9-330.) , and give perf e subsurface k w/400 sx " ete Hines 5/8" J-55 aCl. Circ casing to	tinent dat ocations a 'C'' ST&C : 250 > 1000#
PULL OR AL MULTIPLE CC CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84 4/5/84 4/8/84 4/23/84 Subsurface S 18. 1 hereby	TER CASING	the all p directic ent to the $L7\frac{1}{2}$ " 1 BLM m 2#, 2 50 sx DC 18 co log	change on Fo pertinent details, onally drilled, giv his work.)* hole. Cmt witness: P 8# & 24# 8 "C" + 1% C hrs. Test well.	rm 9-330.) , and give perf e subsurface k w/400 sx " ete Hines 5/8" J-55 aCl. Circ casing to	tinent dat ocations a 'C'' ST&C : 250 > 1000#
PULL OR AL MULTIPLE CC CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84 4/5/84 4/8/84 4/23/84 Subsurface S 18. I hereby SIGNED 1 APPROVED BY	TER CASING	te all p directic ent to th L7 ¹ /2" 1 BLM m 2#, 2 50 sx DC 18 c log Cler	change on Fo pertinent details, phally drilled, giv his work.)* hole. Cmt witness: P 8# & 24# 8 "C" + 1% C hrs. Test well. k DATE <u>5/1/8</u>	rm 9-330.) , and give perf e subsurface k w/400 sx " ete Hines 5/8" J-55 aCl. Circ casing to	tinent dat ocations a 'C'' ST&C : 250 > 1000#
PULL OR AL MULTIPLE CC CHANGE ZON ABANDON* (other) Ge 17. DESCRIE including measure 4/3/84 4/4/84 4/5/84 4/5/84 4/8/84 4/23/84 Subsurface S 18. I hereby SIGNED 1 APPROVED BY	TER CASING	te all p directic ent to th L7 ¹ /2" 1 BLM m 2#, 2 50 sx DC 18 c log Cler	change on Fo pertinent details, phally drilled, giv his work.)* hole. Cmt witness: P 8# & 24# 8 "C" + 1% C hrs. Test well. k DATE <u>5/1/8</u>	rm 9-330.) , and give perf e subsurface k w/400 sx " ete Hines 5/8" J-55 aCl. Circ casing to	tinent dat ocations a 'C'' ST&C : 250 > 1000#

UNP

*See Instructions on Reverse Side