



The drill pad was rotated $\pm 70^\circ$ clockwise to reduce the amount of surface damage.

SUP Exhibit "D"
 SKETCH OF WELL PAD
 Florida Exploration Company
 Well #1 Chama Fed Com
 780' FNL & 1350' FEL Sec. 11-22S-24E