

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND (MORROW)

12. COUNTY OR PARISH

13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☐

OTHER Dual Completion

415 682-7992

RECEIVED

JAN 19 '90

ARIZONA OFFICE

TXO Production Corp. ✓

ADDRESS OF OPERATOR

415 W. Wall, Suite 900 Midland, TX 79701

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

660' FNL, 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3290 GL, 3306 KB

Eddy

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

FULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATION (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) Kill well w/ 2% KCL water.
- 2) Release pkr and TOH w/ tbg.
- 3) TIH w/ Baker "EL" tbg seal connector and 2 3/8" tbg w/ Baker "L" sliding sleeve in string.
- 4) Latch onto Baker "A-3" Lok-set retrievable pkr @ 11,316'; sliding sleeve in open position.
- 5) Kick-off Bone Springs. Turn down sales line to clean-up.
- 6) Close sliding sleeve.
- 7) Pull blanking plug from lok-set pkr.
- 8) Turn Morrow and Bone Springs to sales line.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jay Pulte

TITLE Production Engineer

DATE 1-3-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side