		NM OT CONS COMMISSION C
.n 3160-5 U	NITED STATES	Artesia, NM 598M&PPROVED
	ENT OF THE INTERIOR	Budget Bureau No. 1004-0135
	F LAND MANAGEMENT	Expires: March 31, 1993
BUREAU		5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		NMNM34246
BUNDRY NOTICE	a drill as to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals Use "APPLICATION	o drill or to deepen or reentry to a different reservoir. I FOR PERMIT" for such proposals	
	MIT IN TRIPLICATE	D
Type of Well Oil Gas Well X Well Other	00 7-05-5	8. Well Name and No.
Name of Operator		PFI AMOCO "19" FEDERAL #2
SAMSON RESOURCES COMPAN		
Address and Telephone No. TWO WEST SECOND STREET TU	ILSA, OK 74103 (918) 583-1791 A. OFF	
Location of Well (Footage, Sec., T., R., M., or Survey Description)		FILAREE DOME - DELAWARE
1687' FSL & 2041' FWL SEC. 19-22S-26E		11. County or Parish, State
		EDDY, NEW MEXICO
CHECK APPROPRIA	ATE BOX(s) TO INDICATE NATURE OF NO	
TYPE OF SUBMISSION		Change of Plans
X Notice of Intent	X Abandonment Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report		Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	locations and measured and true vertical depths for all markers	
	PER ATTACHED	
		-
		-
14. I hereby certify that the foregoing is Signed	true and correct	erDateAugust 26, 1994
(This space for Federal or State o	(fice use)	cases alralay
たい(症の) 部分	Title	Date 9/29/94
Approved by		
Conditions of approval, if any:	see attached.	
	any person knowingly and wiltuily to make to any department or agency of	of the United States any false, fictitious or fraudulent statements

*See Instruction on Reverse Side

-

Plug and Abandon Amoco 19 Federal No. 2 Section 19-228-26E Eddy County, NM

1. MIRU workover rig with circulating pump and tank.

2. ND tree. NU BOP.

3. Release packer and POH with tbg and pkr.

4. RUWL. Run and set CIBP at 3632'. Mix and dump 4 sx cement on top of CIBP. RDWL.

** NOTE : Use the following recipe for mixing all cement plugs : - Class C cement with 6.3 gal water per sack, slurry weight 14.8 ppg, yield 1.32 cu ft per sack

5. RIH with muleshoe and tbg. Circulate hole full with 9 ppg mud (approx 86 bbls casing volume, w/o tbg). POH with tbg.

6. RUWL. Run and set CIBP at 2282'. Determine freepoint of 5-1/2" casing at approximately 2200'. Cut and pull csg above FP. RDWL.

7. RIH with tbg to 2275'. Spot 30 sx cement plug in the casing from the BP at 2282' to 2115'(2-7/8", 6.5#, J55 tbg vol 11.9 bbls, max overdisplacement 0.5 bbl). Pull tbg clear of cmt and reverse circulate tbg clean. POH with tbg.

8. RU sand line. RIH and tag cmt plug at 2115'. RD sand line.

9. RIH with tbg to 545'. Spot 40 sx cement plug in casing from 700' to 545' (tbg vol 2.9 bbls, max overdisplacement 0.5 bbl). Pull tbg clear of cmt and reverse circulate tbg clean. POH with tbg.

10. RU sand line. RIH and tag cmt plug at 545'. RD sand line.

11. RIH with tbg to 50'. Spot approx 13 sx cmt from 50' to surface. POH with tbg. ND BOP.

12. RDMO workover rig.

13. Cut off wellhead and install marker.

14. Restore location.



BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Permanent Abandonment of Wells on Federal Lands

Conditions of Approval

1. <u>Approval:</u> Plugging operations shall commence within 90 days from the approval date of plugging procedure.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505)887-6544; for wells in Lea County call (505) 393-3612.

3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show <u>date</u> well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.