		ATES N.M. OH Cons. D	ivision
3160-5	UNITED STA	ATES N.M. On Stragt	FORM APPROVED Budget Bureau No. 1004–0135
1990)	DEPARTMENT OF T	ATES N. ISt Street HE INTERIOR 11 8. 1St Street IANAGEMENT AND NM 88210	
	BOREAU OF EARD M	Allena,	5. Lease Designation and Serial No. NM0554771
:	SUNDRY NOTICES AND R	EPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
o not use this for Us	m for proposals to drill or to e "APPLICATION FOR PERM	deepen or reentry to a different reser	
	SUBMIT IN TRI	PLICATE	7. If Unit or CA, Agreement Designation
Type of Well Oil Gas Well Well	8. Well Name and No. TOG Federal #2		
Well Well Name of Operator	9. API Well No.		
J.C. Williams			
Address and Telephone No	10. Field and Pool, or Exploratory Area		
P.U. Box 16,	East Burton Delaware		
Location of Well (Footage,	11. County or Parish, State		
Sec. 16, T-20		Eddy County, MM	
1980 FSL & 80			
CHECK A	PPROPRIATE BOX(s) TO I		
TYPE OF S	UBMISSION	TYPE OF A	
X Notice of	Intent	Abandonment	Change of Plans
			New Construction
Subsequer	nt Report	Plugging Back	Water Shut-Off
Final Aba	andonment Notice	Altering Casing	Conversion to Injection
		Altering Casing Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
	-Luck Operations (Clearly state III perjugat	Altering Casing Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
	-Luck Operations (Clearly state III perjugat	Altering Casing	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
Describe Proposed or Con give subsurface locat	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35 <sup>1</sup> of cmt.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
Describe Proposed or Con give subsurface locat	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35 <sup>1</sup> of cmt.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths to 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag.	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Fluid.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25	npleted Operations (Clearly state all pertinent tions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" of	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. 1uid.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
Describe Proposed or Corr give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25 4. Cut and 5. Spot 35	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50'	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Fluid.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
<ul> <li>Describe Proposed or Congive subsurface locat</li> <li>1. Set 5-1/2</li> <li>2. Circulate</li> <li>3. Spot 25</li> <li>4. Cut and</li> <li>5. Spot 35</li> <li>6. Spot 35</li> </ul>	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'.	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. 1uid.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 390-200'.	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. 1uid.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 10	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 12-3'.	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. 1uid. esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for to of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 10	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 390-200'.	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. 1uid. esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 15 9. Install	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. Esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log for to of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 15 9. Install	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 12-3'.	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. Esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 15 9. Install	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. Esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 15 9. Install	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. Esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 15 9. Install	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. Esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 15 9. Install	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. Esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 35 9. Install Plugs were o	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths i 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear ok'd by David Glass on	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. Esg. outside of csg. stub. Tag.	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr RECEIVED OCD ARTESIA
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 35 9. Install Plugs were o	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths f 2" CIBP @ 4312', cap w e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. 1uid. 2sg. outside of csg. stub. Tag. h location. 1-25-01 Agent	Conversion to Injection Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for of starting any proposed work. If well is directionally dr
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulate 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 35 9. Install Plugs were o	npleted Operations (Clearly state all pertinent ions and measured and true vertical depths i 2" CIBP @ 4312', cap wi e hole w/ mud laiden f sx 2920-2820'. Tag. pull 2000' of 5-1/2" c sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear ok'd by David Glass on	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Fluid. Esg. outside of csg. stub. Tag. h location. 1-25-01 TideAgent	Conversion to Injection  Conversion to Injection  Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for  of starting any proposed work. If well is directionally dr  RECEIVED  OCD ARTESIA  Date <u>1-25-01</u> AN 0.0 2004
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 6. Spot 35 7. Spot 35 8. Spot 10 9. Install Plugs were o	npleted Operations (Clearly state all pertinent ions and measured and true vertical deputs to 2" CIBP @ 4312', cap w e hole w/ mud laiden ff sx 2920-2820'. Tag. pull 2000' of 5-1/2" co sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear ok'd by David Glass on	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. 2sg. outside of csg. stub. Tag. h location. 1-25-01 TitleAgent	Conversion to Injection  Conversion to Injection  Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for  of starting any proposed work. If well is directionally dr  RECEIVED  OCD ARTESIA  Date <u>1-25-01</u> AN 0.0 2004
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 35 9. Install Plugs were o	npleted Operations (Clearly state all pertinent ions and measured and true vertical deputs to 2" CIBP @ 4312', cap we e hole w/ mud laiden ff sx 2920-2820'. Tag. pull 2000' of 5-1/2" co sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear ok'd by David Glass on foregoing is true and correct	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. 2sg. outside of csg. stub. Tag. h location. 1-25-01 TitleAgent	Conversion to Injection  Conversion to Injection  Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for  of starting any proposed work. If well is directionally dr  RECEIVED  OCD ARTESIA  Date <u>1-25-01</u> AN 0.0 2004
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 6. Spot 35 7. Spot 35 8. Spot 10 9. Install Plugs were o	npleted Operations (Clearly state all pertinent ions and measured and true vertical deputs to 2" CIBP @ 4312', cap we e hole w/ mud laiden ff sx 2920-2820'. Tag. pull 2000' of 5-1/2" co sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear ok'd by David Glass on foregoing is true and correct	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. 2sg. outside of csg. stub. Tag. h location. 1-25-01 TitleAgent	Conversion to Injection  Conversion to Injection  Dispose Water (Nose: Report results of multiple completion on W Completion or Recompletion Report and Log for  of starting any proposed work. If well is directionally dr  RECEIVED  OCD ARTESIA  Date <u>1-25-01</u> AN 0.0 2004
Describe Proposed or Com give subsurface locat 1. Set 5-1/2 2. Circulat 3. Spot 25 4. Cut and 5. Spot 35 6. Spot 35 7. Spot 35 8. Spot 19 9. Install Plugs were of 14. I hereby certify part the Signed (This space for Federal	npleted Operations (Clearly state all pertinent ions and measured and true vertical deputs to 2" CIBP @ 4312', cap we e hole w/ mud laiden ff sx 2920-2820'. Tag. pull 2000' of 5-1/2" co sx, 50'inside and 50' sx 1250-1150'. sx 300-200'. sx 13-3'. dry hole marker, clear ok'd by David Glass on foregoing is true and correct Muno for State office use) iG. SGD.) DAVID F. GLAS	Altering Casing Other details, and give pertinent dates, including estimated date for all markers and zones pertinent to this work.)* 7/ 35' of cmt. Tuid. 2sg. outside of csg. stub. Tag. h location. 1-25-01 TitleAgent	Conversion to Injection Competition results of multiple completion on W Completion or Recompletion Report and Log for to of starting any proposed work. If well is directionally dr RECEIVED OCD ARTESIA OCD ARTESIA OCD ARTESIA OCD ARTESIA OLI Date 1-25-01 IEER JAN 29 2001

• 500	Instruction	on	Reverse	Side