| November 1933 Formerly 9-331) UNITED STATES SUBMIT IN TRIPLICATE DEPARTMENT OF THE INTERIOR OF THE INTERIOR OF SUB- BUREAU LAND MANAGEMENT IS STON | 5 LEASE DESIGNATION AND BERIAL |
|---|--|
| Do not use this form for proposais to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT_" for such proposals.) | B IF INDIAN. ALLOTTEE OR TRIBE NAME |
| WELL GAS WELL OTHER | 7. UNIT AGREEMENT NAME |
| Marathon Oil Company - 3. ADDRESS OF OPERATOR | 8. FARM OR LEASE NAME Indian Basin "A" |
| P. O. Box 552, Midland, Texas 79702 | 9. WELL NO. |
| tocation of well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface | 10. FIELD AND POOL OR WILDCAT |
| Unit Letter K 1650' FSL & 1650' FWL | Indian Basin (Upper Penn) 11. SBC., T., B., M., OB BLK. AND BURVEY OR ARMA |
| 14. PERMIT NO 15 ELEVATIONS (Show whether DF. RT. OR. etc.) | Sec. 22, T21S, R23E |
| 30-105-26011 3880' GR | 12. COUNTY OR PARISE 13. STATE Eddy NM |
| 18. Check Appropriate Box To Indicate Nature of Notice, Report, or C | - |
| NOTICE OF INTENTION TO : | |
| | ENT REPORT OF: |
| FRACTURE TREAT WULTIPLE COMPLETE WATER SHUT-OFF | REPAIRING WELL |
| SHOOT OR ACIDIZE X ABANDON. SHOOTING OR ACIDIZING | ALTEBING CASING |
| REPAIR WELL CHANGE PLANS (Other) | |
| Other) and change out tubing | of multiple completion on Well etion Report and Log form.) |
| 17. DESCRIDE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any nent to this work.) • | |
| <pre>Marathon Oil Company proposes to move on the above well on Decemb the existing 2 3/8" tubing with 2 7/8" tubing and reperforate and formation. Following is the proposed procedure: 1. Test safety anchors. 2. Install H₂S safety equipment. 3. MIRU PU. 4. ND wellhead & NU BOP's.</pre> | per 4, 1989 to replace d acidize the Upper Penn |
| 5. POOH, laying down 2 3/8" J-55 tubing. 6. Reperforate Upper Penn w/4 JSPF from 7319'-24', 34'-38', 5 7. PU & RIH w/2 7/8" J-55 tubing & packer. 8. Acidize w/2000 gals 15% acid. | |
| 9. Release pkr, knock ball sealers off perforation, and reset | pkr at 7195'. |
| 10. ND BOP's & NU wellhead. 11. Swab well in & turn to production. | |
| 12. RD PU. | RECEIVED |
| If you have any questions, please feel free to call me at (915) | 682-1626. DEC 26 '89 O. C. D. |
| 18. I hereby certify that the foregoing is true and correct | ARTESIA, OFFICE |
| SIGNED J. R. Jenkins TITLE Hobbs Production Sup't. | DATE 11-22-89 |
| (This space for Federal or State office use) | |
| APPROVED BY TITLE TITLE PEROLEUM ENGINEER | DATE 11.37.84 |

*See Instructions on Reverse Side