,		
	- <u>)</u> .	151
		61.
UNITED STATES		M APPROVED
Interior (Interior Contractor Con	Budget Bu Expires	reau No. 1004-0135 : March 31, 1993
BUREAU OF LAND MANAGEMENT	5. Lease Design	ation and Serial No.
AND REPORTS ON W		4-15881
SUNDRY NOTICES AND REPORTS ON W Do not use this form for proposals to drill or to deepen or reentr	v to a different reservoir.	ottee or Tribe Name
Use "APPLICATION FOR PERMIT-" for such p	roposals	
SUBMIT IN TRIPLICATE	7. If Unit or C/	A, Agreement Designation
. Type of Well	8. Well Name an	4 No.
Oil X Gas Well Other		<u>UR Federal Com</u>
Name of Operator(505)YATES PETROLEUM CORPORATION(505)	748-1471) 9. API Well No.	UN TEUETAT COM
Address and Telephone No.	30-	015-26038
105 South 4th St., Artesia, NM 88210		ol, or Exploratory Area lat Morrow, East
Location of Well (Footage, Sec., T., R., M., or Survey Description)		the second s
1980' FSL & 990' FWL of Section 12-T20S-R29E (Un		
		dy Co., NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATU	JRE OF NOTICE, REPORT, OR OTH	ER DATA
	TYPE OF ACTION	
		Plans
L_ Notice of Intent		struction
Subsequent Report		ine Fracturing
		11-Off n to Injection
Final Abandonment Notice	cidize perforations Dispose	÷
I IX Other A		
L& J Other _A	(Note: Report res	ults of multiple completion on Well completion Report and Log form }
3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent	(Note: Report res Completion or Ri dates, including estimated date of starting any proposed worl	completion Report and Log form }
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 	(Note: Report ret Completion or Ri dates, including estimated date of starting any proposed worl pertinent to this work.)*	completion Report and Log (orm) If well is directionally drilled,
3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones	(Note: Report ret Completion or R dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz	completion Report and Log form) . If well is directionally drilled, ed perforations
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 	(Note: Report ret Completion or R dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz	completion Report and Log form) . If well is directionally drilled, ed perforations
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 	(Note: Report rec Completion or R dates, including estimated date of starting any proposed worl pertiment to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form) . If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form) . If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form) . If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form) . If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department 	(Note: Report rec Completion or Re dates, including estimated date of starting any proposed worl pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron	completion Report and Log form } c. If well is directionally drilled, ed perforations
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department DEC 1550 RECEIVED OCD - ARTESIA 	(Note: Report rec Completion or Re Completion or Re pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron nt.	Ecompletion Report and Log form } t. If well is directionally drilled, ed perforations control HCL
 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department DEC 1550 RECEIVED OCD - ARTESIA 	(Note: Report rec Completion or Re Completion or Re pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron nt.	completion Report and Log form } c. If well is directionally drilled, ed perforations
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department DEC 1550 RECEIVED OCD - ARTESIA OCD - ARTESIA Operation 	(Note: Report rec Completion or Re Completion or Re pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron nt.	<pre>completion Report and Log form } t. If well is directionally drilled, ed perforations control HCL </pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical depths for all markers and zones 12-2-98 - Moved in and rigged up pulling unit. 10727-10866' (Strawn) (via 2-7/8" tubing) with acid and ball sealers. Swabbing. 12-3-98 - Swab & flow test. Shut well in. 12-4-98 - Released well to production department DEC 1550 RECEIVED OCD - ARTESIA OCD - ARTESIA A thereby cirplify that the foregoing if fue and correct Signed WMt, Mt, Correct 	(Note: Report rec Completion or Re Completion or Re pertinent to this work.)* Rigged up treesaver. Acidiz 20000 gallons 15% gelled iron nt.	Ecompletion Report and Log form } t. If well is directionally drilled, ed perforations control HCL

n an tai e anti tailar e la c

×.