August 1999)	UNIA STAT DEPARTMENT OF THE		· · · ·	Oil Cons. 5. 1st Stre	1	FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000	0151
	BUREAU OF LAND MAN		Artes	sia, NM 88			
SUNDR Do not use th	Y NOTICES AND REP his form for proposals t	ORTS ON W				NM-5/633	
abandoned w	nis form for proposals t ell. Use Form 3160-3 (Af	PD) for such j	proposals.		6 If India	an, Allottee or Tribe Name	
SUBMIT IN TR	IPLICATE - Other inst	ructions on	reverse :		7. If Unit	or CA/Agreement, Name an	d/or No
Type of Well				2993031	Ţ		
🖾 Oil Well 🛄 Gas Well 🕻	Other		13	4	P& Well	Name and No.	
2 Name of Operator Ray V	Vestall Operating	-			5 9. API W	Huron Federal # 1	·
3a Address	·····	3b. Phone	No functude	areneodelVEL		30-015-26450	
P.O. BOX 4, Location of Well (Footage, Sec	Loco Hills, NM 882		<u> </u>	CD - ARTESIA		and Pool, or Exploratory Are	
e notation of write onlage, set	r , K., W , or Survey Descripti	(11)				st Burton Deleward	e
2310' FSL & 330' FWL	, Section - 15 Towsh	ip - 205 Ra	ange - 29	E		y of the long of the	
						Eddy,NM	
	PROPRIATE BOX(ES)				REPORT, O	R OTHER DATA	
TYPE OF SUBMISSION	<u> </u>	<u> </u>		E OF ACTION			
Notice of Intent	Acidize	Deepen Fracture	Tract	Production (StaReclamation	nt/Resume)	Water Shut-Off	
Subsequent Report	Casing Repair	New Cor		Recomplete		 Well Integrity Other 	
	Change Plans	X Plug and		Temporarily A	bandon		
Final Abandonment Notice	Convert to Injection	Plug Bac	k	Water Disposal		·········	· · • ·
Attach the Bond under which (following completion of the in	volved operations. If the operation inal Abandonment Notices shall	provide the Bond tion results in a r	l No on file	with BLM/BIA. Rep entropy or recomplete	juired subsequ	ient reports shall be filed wi	thin 30 days
following completion of the in testing has been completed. F determined that the site is ready	the work will be performed or volved operations. If the opera inal Abandonment Notices sha for final inspection)	provide the Bond tion results in a r I be filed only a	l No on file nultiple comj ifter all requi	with BLM/BIA. Rep entropy or recomplete	juired subsequ	ient reports shall be filed wi	thin 30 days
Attach the Bond under which i following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @	4450'. Shot squeeze	provide the Bond tion results in a r I be filed only a	l No on file nultiple comj ifter all requi	with BLM/BIA. Re oletion or recompleti- rements, including re	juired subsequ	ient reports shall be filed wi terval, a Form 3160-4 shall ve been completed, and the	thin 30 days
Attach the Bond under which it following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs	4450'. Shot squeeze	provide the Bond tion results in a r I be filed only a	l No on file nultiple comj ifter all requi	with BLM/BIA. Rep entropy or recomplete	juired subsequ	Hent reports shall be filed with terval, a Form 3160-4 shall be been completed, and the term $\frac{1}{1000} \sqrt{ED}$	thin 30 days
Attach the Bond under which if Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs of Spot 25 sxs of	4450'. Shot squeeze on CIBP @ 4450' @3366'	provide the Bond tion results in a r I be filed only a	l No on file nultiple comj ifter all requi	with BLM/BIA. Re oletion or recompleti- rements, including re	juired subsequ on in a new in clamation, ha	Hent reports shall be filed wi terval, a Form 3160-4 shall be been completed, and the intervention of the shall intervention of the shall be filed with the shal	thin 30 days be filed once operator has
Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs (Spot 25 sxs (Heavy gel be)	4450'. Shot squeeze on CIBP @ 4450' 3366' 0 3056' tween plugs	holes @ 19	l No on file nultiple comp ifter all requi	with BLM/BIA. Rei oletion or recompleti- rements, including re	puired subsequent in a new in in a new in inclamation, ha	Hent reports shall be filed wi terval, a Form 3160-4 shall be been completed, and the ETTTADYED AAT 2001 LES BABYAK IRC: EUM ENGINEEF	thin 30 days be filed once operator has
 Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs of Spot 25 sxs of Spot 25 sxs of Heavy gel be Cmt. down 4 	4450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s	holes @ 19	l No on file nultiple comp ifter all requi 900'.	with BLM/BIA. Replayers Recompletion or recompletion or recompletion or recompletion of the second s	casing w	ient reports shall be filed wi terval, a Form 3160-4 shall we been completed, and the infrince in a completed infrince in a completed infrince in a completed infrince in a completed it is a completed in a	thin 30 days be filed once operator has
2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs (Spot 25 sxs (Heavy gel be	4450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s	holes @ 19	l No on file nultiple comp ifter all requi 900'.	with BLM/BIA. Replayers Recompletion or recompletion or recompletion or recompletion of the second s	Casing work	A 2001 LES BABYAK IRC: EUM ENGINEEF with 475 sxs "C" nea and as to plugging of	thin 30 days be filed once operator has at.
 Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs of Spot 25 sxs of Spot 25 sxs of Heavy gel be Cmt. down 4 2/27/01 - Dug out cella 	4450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s ar, cut off casing, Fill	holes @ 19 sueeze hole to top with	I No on file nultiple comp ifter all requi 900'. (es @ 190 redimix.	with BLM/BIA. Replayers Recompletion or recompletion or recompletion or recompletion of the second s	Casing w ole marke Appro Liabel	A 2001 LES BABYAK IRC: EUM ENGINEEF with 475 sxs "C" nea er. by under bond is retain	thin 30 days be filed once operator has at. at. the well bo red until
 Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs of Spot 25 sxs of Spot 25 sxs of Heavy gel be Cmt. down 4 2/27/01 - Dug out cellation (Witnessed b) 	4450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s ar, cut off casing, Fill by - Jim Amos - BLM	holes @ 19 sueeze hole to top with	I No on file nultiple comp ifter all requi 900'. (es @ 190 redimix.	with BLM/BIA. Replayers Recompletion or recompletion or recompletion or recompletion of the second s	Casing w ole marke Appro Liabel	A 2001 LES BABYAK IRC: EUM ENGINEEF with 475 sxs "C" nea and as to plugging of	thin 30 days be filed once operator has at. at. the well bo red until
 Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs if Spot 25 sxs if Spot 25 sxs if Heavy gel be Cmt. down 4 2/27/01 - Dug out cellation (Witnessed b) 	4450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s ar, cut off casing, Fill by - Jim Amos - BLM	holes @ 19 sueeze hole to top with	I No on file nultiple comp ifter all requi 900'. (es @ 190 redimix.	with BLM/BIA. Replayers Recompletion or recompletion or recompletion or recompletion of the second s	Casing w ole marke Appro Liabel	A 2001 LES BABYAK IRC: EUM ENGINEEF with 475 sxs "C" nea er. by under bond is retain	thin 30 days be filed once operator has at. at. the well bo wed until
 Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs (Spot 25 sxs (Spot 25 sxs (Heavy gel be Cmt. down 4 2/27/01 - Dug out cellated (Witnessed be cont. 14 Thereby certify that the forego 	4450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s ar, cut off casing, Fill by - Jim Amos - BLM	holes @ 19 sueeze hole to top with	I No on file nultiple comp ifter all requi 900'. (es @ 190 redimix.	with BLM/BIA. Replayers Recompletion or recompletion or recompletion or recompletion of the second s	casing w ole market Casing w Ole market Surfa	A Provide a sto plugging of the provider the store of the	thin 30 days be filed once operator has at. the well bo red until
 Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs (Spot 25 sxs (Spot 25 sxs (Heavy gel be Cmt. down 4 2/27/01 - Dug out cellated (Witnessed be 14 Thereby certify that the forego 	4450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s ar, cut off casing, Fill oy - Jim Amos - BLM	holes @ 19 sueeze hole to top with	No on file nultiple comp filer all requi 000'. (es @ 19(redimix.)	with BLM/BIA. Repletion or recompleting reco	casing w ole market Casing w Ole market Surfa	A Provide a sto plugging of the provider the store of the	thin 30 days be filed once operator has at. the well bo red until
 Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs of Spot 25 sxs of Spot 25 sxs of Spot 25 sxs of Heavy gel be Cmt. down 4 2/27/01 - Dug out cellation (Witnessed b) 14 Thereby certify that the foregot Name (Printed Typed) 	A450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s ar, cut off casing, Fill by - Jim Amos - BLM ing is true and correct Rene' Mathews	holes @ 19 sueeze hole to top with - Carlsbad	Do on file nultiple comp filer all requi 000'. (es @ 190 redimix.) Title Date	With BLM/BIA. Repletion or recompleting recompleting the second s	Casing w ole marke Appro Liabil Secretary	A Provide a sto plugging of the provider the store of the	thin 30 days be filed once operator has at. at. the well bo wed until
Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs (Spot 25 sxs (Spot 25 sxs (Heavy gel be Cmt. down 4 2/27/01 - Dug out cella (Witnessed k 14 Thereby certify that the forego Name (Printed Typed)	A450'. Shot squeeze on CIBP @ 4450' @3366' @ 3056' tween plugs 1/2" casing through s ar, cut off casing, Fill by - Jim Amos - BLM ing is true and correct Rene' Mathews	holes @ 19 sueeze hole to top with - Carlsbad	Do on file nultiple comp ifter all requi 000'. (es @ 190 redimix.) Title Date tAL OR ST	With BLM/BIA. Repletion or recompletinents, including re 00' & up 8 5/8' Inslalled dry h Production S 5/11/01 ATE OFFICE US	Casing w ole marke Appro Liabil Secretary	A Constant in the filed with the filed with the first of the filed with the	thin 30 days be filed once operator has at. the well bo red until
Attach the Bond under Which I following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs Spot 25 sxs (Spot 25 sxs (Heavy gel be Cmt. down 4 2/27/01 - Dug out cella (Witnessed k 14 Thereby certify that the forego Name (Printed Typed) Signature Approved by Conditions of approval. If any, and certify that the applicant holds be	the work will be performed or volved operations. If the opera inal Abandonment Notices shail for final inspection) 4450'. Shot squeeze on CIBP @ 4450' @ 3366' @ 3056' tween plugs 1/2" casing through s 1/2" casing through s ar, cut off casing, Fill by - Jim Amos - BLM ing is true and correct Rene' Mathews Charles SPACE e attached Approval of this me cal or equitable title to those t	holes @ 19 holes @ 19 sueeze hole to top with - Carlsbad	Do on file nultiple comp ifter all requi 2000'. () es @ 190 redimix.) Title Date tAL OR ST	Production S 5/11/01 ATE OFFICE US	Casing w ole marke Appro Liabil Secretary	A Provide a sto plugging of the provider the store of the	thin 30 days be filed once operator has at. the well bo red until
Attach the Bond under which if following completion of the in testing has been completed. F determined that the site is ready 2/23/01 - Set CIBP @ 2/26/01 - Spot 25 sxs of Spot 25 sxs of Spot 25 sxs of Heavy gel be Cmt. down 4 2/27/01 - Dug out cella (Witnessed b 14 Thereby certify that the forego Name (Printed Typed) Signature	the work will be performed or proved operations. If the operations in Abandonment Notices shall be performed or provided operations. If the operation of the operation of this mean or final inspection of the operation of the ope	holes @ 19 holes @ 19 sueeze hole to top with - Carlsbad	Do on file nultiple comp ifter all requi 2000'. (200)) ((200))) (200)) (((with BLM/BIA. Repletion or recompletinents, including re 00' & up 8 5/8' Inslalled dry h Production S 5/11/01 ATE OFFICE US Including re	Casing w ole marke Liabel Secretary	A Completed and the filed witerval, a Form 3160-4 shall be filed witerval, a Form 3160-4 shall be filed witerval, a Form 3160-4 shall be filed witer and the completed, and the completed, and the completed as to plugging of the filed witer bond is retained as to plugging of the processor of the processor of the completed as to plugging of the comple	thin 30 days be filed once operator has at. at. the well bo red until sted.



a Maranta **ata**ng