

dsf  
Op

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

RECEIVED

NOV 25 1991

WELL API NO.	30-015-26580
Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry	7. Lease Name or Unit Agreement Name  State "2"
2. Name of Operator H. L. Brown, Jr.	8. Well No. 1
3. Address of Operator P. O. Box 2237, Midland, Texas 79702	9. Pool name or Wildcat Wildcat <i>Abc</i>
4. Well Location Unit Letter <u>F</u> : <u>1700</u> Feet From The <u>North</u> Line and <u>1800</u> Feet From The <u>West</u> Line Section <u>2</u> Township <u>21-S</u> Range <u>22-E</u> NMPM <u>Eddy</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4100.9 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-26-91 Drilled to 4261'. Ran DST #1 from 4121-4261, No shows.  
7-27-91 Drilled to 4310'. Ran GR/SDL/DNS & DILL.  
7-27-91 Began plugging well: Set 35 sx plug @ 3978-3878  
Set 35 sx plug @ 1616-1516  
Set 35 sx plug @ 1350-1240  
7-28-91 WOC. Tagged plug @ 1240' and set 35 sx plug @ 400-300  
set 10 sx plug @ surface  
7-28-91 Cut off casing, welded plate, cleaned location.  
7-28-91 Well P&A.

Post ID-2  
1-17-92  
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark A. Gosch TITLE Production Engineer DATE 11-21-91  
TYPE OR PRINT NAME Mark Gosch TELEPHONE NO.

(This space for State Use)  
APPROVED BY [Signature] TITLE Field Rep DATE 4/17/93  
CONDITIONS OF APPROVAL, IF ANY: