

LOWE STATE #303/28/98

TMD: 8217 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 10:30 06A D TRIPPING IN HOLE W/NEW BHA
 10:30 13:45 25A DRILL OUT/D/V TOOL /TEST 1000#-OK
 13:45 15:30 06A D TRIPPING IN HOLE
 15:30 17:30 25A DRILL OUT/FC ,CEMENT, FS
 17:30 20:30 05A A CIRC & COND MUD /DISPLACED HOLE W/FW /
 CLEAN PITS/ MIX AND COND MUD
 20:30 00:30 02A A DRILLING 8161-8217 (56')
 00:30 04:00 06A A TRIPPING FOR BIT #6
 04:00 05:00 06A A TRIPPING IN HOLE

03/29/98

TMD: 8305 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 06:00 06A A TRIPPING IN HOLE W/DC
 06:00 06:30 09A CUT DRLG LINE
 06:30 08:00 06A A TRIPPING IN HOLE
 08:00 09:00 03A A REAMING 60' TO BOTTOM W/ 3PT ROLLER REAMER
 09:00 10:15 02A A DRILLING 8217'-8231' (14') LOST 100# PUMP
 PRESSURE
 10:15 10:45 23B D PROBLEMS /CK PUMP /PUMP SOFT LINE
 10:45 14:00 23B D PROBLEMS / CHAIN OUT OF HOLE LOOKING FOR
 LEAK/ CK BIT /BAD CONE SEAL /CK REAMER /
 CHANGE OUT BOTH
 14:00 19:00 23B D PROBLEMS / TRIP CHECK DC IN HOLE/ LD 6 W/
 SWELLED BOXES /PU 6 NEW DC
 19:00 21:15 23B D PROBLEMS / TIH W/ BIT #7
 21:15 05:00 02A A DRILLING 8231'-8305' (74') W/ NO PROBLEMS

03/30/98

TMD: 8530 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 05:00 02A A DRILLING 8305-8530 (225')

03/31/98

TMD: 8785 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 07:45 02A A DRILLING 8530-8552 (22')
 07:45 08:15 10A SURVEYS 1.50 DEG-8512
 08:15 05:00 02A A DRILLING 8552-8785 (233')

04/01/98

TMD: 9035 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 04:00 02A A DRILLING 8785-9030 (245')
 04:00 04:30 10A SURVEYS 2.0 DEG-8990'
 04:30 05:00 02A A DRILLING 9030-9035 (5')

04/02/98

TMD: 9230 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 05:00 02A A DRILLING 9035'-9230' (195')