Submit 3 Copies to Appropriate District Office	. State of New Me En , Minerals and Natural Re	exico esources Department	C15	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO 2040 Pacheco St. Santa Fe, NM 8		WELL API NO. 4 30-015-30932 .	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210		A	sIndicate Type of Lease	STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		RECEIVED 3	6State Oil & Gas Lease	
(DO NOT USE THIS FORM FOR PR	ICES AND REPORTS ON WELL OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)	ISARTESTA	7Lease Name or Unit A Davis 7	greement Name
Type of Well: OIL GAS V				
2Name of Operator	CONE	TATA	sWell No. 1	
Pogo Producing Company 3Address of Operator		0 H L 10 K p 8 2003 0000	Pool name or Wildcat	
P. O. Box 10340, Midland, TX 79	702-7340		McMillian Morrow	· · · · · · · · · · · · · · · · · · ·
4Well Location Unit Letter <u>M</u> 660	Feet From The South	Line and660	Feet From The	West Line
Section 7	Township 20S	Range 27E		Eddy County
	1₀Elevation (Show whether DF 3341' GL	; RKB, RT, GR, etc.)		and a store that is
11 Check A	Appropriate Box to Indicate N	lature of Notice, Re	eport, or Other D	ata
NOTICE OF I	NTENTION TO:	SUB	SEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS.	PLUG AND ANBANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEN	IENT JOB	
OTHER:		OTHER: Spud, Set S	Surface, Intermediate	e & Production Csg
work) SEE RULE 1103. Spud & Set Surface Csg-MIRU 1815 hrs CST 01/25/00. Ran 1. "C" + 2% CaCl2. Plug down @ psi. NU BOP's & test to 1000#	ions (Clearly state all pertinent details, and gi TMBR/Sharp #10. Spud well @ 2 2 jts 13-3/8" 68# J-55 BT&C csg. 0300 hrs 01/26/00. Circ 10 sxs to ok.	2300 hrs CST 01/24/00 TPGS @ 500'. BJ cm o surface. WOC 35 hrs). Drld 17-1/2" hole t'd w/ 230 sxs "C" L s. Make cut-off. W	to 500'. TD reached @ ite followed by 200 sxs Cl eld on WH & test to 500
shoe @ 2900'. Float collar @ 2 14.8 ppg. Circ 100 sxs to surfa 1000#. NU BOP's and test ok.	nole to 2900'. TD reached @ 1100 2857'. BJ cmt'd w/ 535 sxs Cl "C" ice. Plug down @ 1700 hrs CST ()2/01/00. ND BOP's a	nd make cut-off. W	eld on WH & test to
jts 5-1/2" 17# N-80 & L-80 csg. sxs Cl "H" + .3% FL50 + .3% C	le to 9297'. Drld 7-/78" hole from Float shoe @ 10,500'. Float colla D32 + .15% R3. Circ 56 sxs. Cm 35:65 POZ followed by 100 sxs "C ut-off. Weld on WH. TOC @ 472	t'd 2nd stage w/ 1008	sxs "C" + .15% FL5 lisplace cmt. Plug o	0 + 75% CD32 + 12#/sx
		John and ballaf		
I hereby certify that the information abov	e is true and complete to the best of my know	TITLE Operation Tech		DATE 03-09-00
SIGNATURE	dia			TELEPHONE NO. 915-685-8100
TYPE OR PRINT NAME Cathy Tomber		<u></u>		
APPROVED BY	W. Sum BA	тпсе	ut Segaroi	DATE 3-14-00
CONDITIONS OF APPROVAL, IF ANY:				