

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYCopy J. F.
to
SUBMIT IN TR CATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
NM-0937-A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Plugged and abandoned	6. IF INDIAN, ALLOTTEE OR TRIBE NAME ---
2. NAME OF OPERATOR Humble Oil & Refining Company	7. UNIT AGREEMENT NAME Huapache Unit
3. ADDRESS OF OPERATOR Box 2100, Hobbs, New Mexico	8. FARM OR LEASE NAME ---
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2042 FNL, 1618 FEL of Sec. 14, T-24-S, R-22-E, SW/4 of NE/4 of Sec. 14, Eddy County, New Mexico	9. WELL NO. 5
14. PERMIT NO. ---	10. FIELD AND POOL, OR WILDCAT Wildcat
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5352 DF	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T-24-S, R-22-E
	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) **PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Proposed plugs to abandoned are to be set as follows:

Plug #1 from Surface to 15' with 10 sxs. cement.
Plug #2 from 1348' to 1448' with 35 sxs. cement.
Plug #3 from 1980' to 2180' with 70 sxs. cement.
Plug #4 from 3450' to 3550' with 40 sxs. cement.
Plug #5 from 4620' to 4800' with 50 sxs. cement.

Verbal permission to set plugs as listed above received on 1-11-65 by our Mr. Bevill from Mr. Knauf, U. S. G. S. representative in Artesia, New Mexico.

** Original plan was to re-enter and deepen hole, however, well was dry.

RECEIVED

JAN 22 1965

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED


TITLE Dist. Adm. Supvr.

DATE 1-12-65

(This space for Federal or State office use)

TITLE

DATE



*See Instructions on Reverse Side