

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE
(Other instructive
verse side)ATE*
1 re-Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC-064200

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "D"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Black River Penn (Gas)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 12, T24S, R26E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Joseph I. O'Neill, Jr.

3. ADDRESS OF OPERATOR

410 West Ohio, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State law.
See also space 17 below.)
At surface

Unit Letter P E

660' FSL & 660' FSL, Sec 12, T24S, R26E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3244' GL, 3262' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

☐
☐
☒
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐☐
☐
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Plug and abandon depleted gas zone.

13-3/8" casing set @ 291' & cemented to surface.

9-5/8" casing set @ 6819' & cemented to surface. DV tool set @ 5110'.

5 1/2" casing set @ 11,918', top of cement @ 10,300'.

Perforations @ 11,560-11,580', 11,834-11,848' & 11,860-11,864'.

2-3/8" tubing set @ 11,675' & Baker packer @ 11,485'.

Packer stuck @ this time.

Plan:

(1) Squeeze 50 sacks cement into perforated intervals & displace via 2" tubing to 11,480'.

(2) Recover as much tubing & 5 1/2" casing as possible.

(3) Plug #2 - 150' - 75 sacks cement above 5 1/2" stub.

(4) Plug #3 - 150' - 75 sacks in & out of 9-5/8" casing @ 6819'.

(5) Plug #4 - 20 sacks in top of 9-5/8" casing.

(6) Well cap & marker on top.

(7) * If 5 1/2" casing recovered below 8000', will put 150' plug @ 8000'.

RECEIVED
FEB 24 1975
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert R. R. R.

TITLE

Drilling Foreman

DATE

2-20-75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side