

April 16, 1962

Everett D. Burgett  
102 South Canal  
Carlsbad, New Mexico

Re: Myers Union Well #1  
Unit-L Sec. 11-23-27  
Eddy County, New Mexico

Dear Sir:

Mr. Gressett inspected your dry hole located NE SE in section 11-23-27, he found no location marker. The pit not filled, and junk on location. Please send C-103 on each string of pipe and amount of cement used on each string, also C-103 & C-105 (well record) as to just how it was plugged, how much pipe pulled and soforth.

We want this done at once as we feel you have had ample time.

Very truly yours,

OIL CONSERVATION COMMISSION

MLA/jw

M. L. Armstrong  
Supervisor, District #2