

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-05840
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name STATE AA-2
8. Well No. 1
9. Pool name or Wildcat SWD: DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator ARCO Permian	
3. Address of Operator P.O. Box 1610 Midland, TX 79702	
4. Well Location Unit Letter A : 660 Feet From The NORTH Line and 660 Feet From The EAST Line Section 2 Township 23S Range 31E NMPM EDDY County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3459 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: RE-ENTRY/SWD <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-23/24: DRILL AND CLEAN OUT 7-7/8" HOLE TO PRIOR TD AT 5190'.
5-25: REACH TD AT 5800'.
5-26: RUN 5-1/2" CASING AND CEMENT TO 2215' PER TEMP. SURVEY.
7-19: PERF'D AND FRAC'D 5610-5670.
7-22: PERF'D AND FRAC'D 5354-5374.
8-7: PERF'D 5123-5282.
8-8: PERF'D AND FRAC'D 4929-5282.
8-20: PERF'D AND FRAC'D 4489-4611.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Elizabeth A. Casbeer TITLE REG./COMPLIANCE DATE 9/17/97
TYPE OR PRINT NAME ELIZABETH A. CASBEER TELEPHONE NO. 915-688-5570

(This space for State Use)

APPROVED BY SUPERVISOR, DISTRICT II TITLE _____ DATE SEP 26 1997
CONDITIONS OF APPROVAL, IF ANY: _____