

to 2000# at end of test. Control valves operated as indicated on closing unit manifold at end of test. Bop extentions were not hooked up crew changing out kelly. No test desired to top of casing using packer, nor to the lower kelly cock, or to the drill pipe safety valve (not in rig inventory at time of test).

YELLOW JACKET TOOLS AND SERVICES, INC.

ODESSA, TEXAS

Test made by Billie Brogden *Billie Brogden*