

NO. OF COPIES RECEIVED	1
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

NOV 30 1970

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1902
7. Unit Agreement Name -
8. Farm or Lease Name N.M. 'DD' State Com.
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator TEXACO Inc. 3. Address of Operator P.O. BOX 728 - HOBBS, NEW MEXICO 88240 4. Location of Well UNIT LETTER G , 1655 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 24S RANGE 26E NMPM.	15. Elevation (Show whether DF, RT, GR, etc.) 3415' GR
---	--

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO Inc. proposes to plug and abandon subject well as follows:

1. Squeeze perforations 9933' - 9960' w/50 sx Class C Cement.
Re-squeeze w/50 sx Class C Cement.
2. Run and set bridge plug @ 7975'. Spot 10 sx Class H cement from 7975-7935'.
3. Load hole w/11.5 ppg mud.
4. Cut off and pull 7-5/8" casing @ 1545'.
5. Spot 100 sx Class C cement w/2% Cacl from 1540' to 1310'.
6. Spot 50 sx class C cement w/2% Cacl from 90' to surface.
7. Install 4" marker extending 4' above ground level and clean location.

Note: Verbal approval to plug and abandon by NMOCC - November 2, 1970.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. E. Morgan TITLE District Superintendent DATE November 25, 1970

APPROVED BY B. L. Stambaugh TITLE OIL AND GAS INSPECTOR DATE DEC 1 1970

CONDITIONS OF APPROVAL, IF ANY: