Submit 3 Copics to Appropriate
District Office

State of New Mexico ais and Natural Resources Department Energy, N

WELL API NO.

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Forms C-103
Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-015-2040/	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES				
(DO NOT USE THIS FORM FOR PROPOS	7. Lease Name or Unit Agreement Name Spencer A			
1. Type of Well:	FOR SUCH PROPOSALS.)			
OF MET GYS	OTHER		008638	
2. Name of Operator OXY USA Inc.	/	16696	8. Well No.	
3. Address of Operator P.O. Box 5025	0 Midland, TX	79710	9. Pool name or Wildcat Wildcat	
4. Well Location	Engline South	Line and 198	Feet From The East Line	
Unit Letter::			Eller -	
Section 30	Township 32 S Ray /// 10. Elevation (Show whether is	oge 27E OF, RKB, RT, GR, esc.)	NMPM Eddy County	
(
	ropriate Box to Indicate N	Nature of Notice, R	Report, or Other Data	
NOTICE OF INTER	ITION TO:	SUE	SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
OTHER:	□	OTHER:		
12. Describe Proposed or Completed Operations	(Clearly state all pertinent details, as	nd give persinent dates, inci	uding estimated date of starting any proposed	
work) SEE RULE 1103.				
	SEE OTHER	SIDE	RECEIVED	
			DL 27 1915	
I hereby certify that the information above is true an	d complete to the best of my knowledge an	Regulatory	Analyst <u>pate</u> 7/25/95	

(This space for State Use)

TYPE OR FRINT NAME

APPROVED BY -

SIGNATURE -

ORIGINAL SIGNED BY TIM W. GUM

DISTRICT II SUPERVISOR

David Stewart

- TITLE -

AUG 1 0 1995

TELEPHONE NO.9 156855717

ATTACHMENT C-103 OXY USA INC. SPENCER A #1 SEC 30 T22S R27E EDDY COUNTY, NM

- 1. MIR'J pulling unit. ND WH. NU BOP. PU 2 3/8" tbg & RIH and tag cmt plug @ 5104'.
- 2. POOH to 2700'. RU Service Co. & spot 200' cmt plug up to 2500'.
- 3. POOH to 1700'. Spot 200' cmt plug across DV tool up to 1500'.
- 4. POOH to 450'. Spot 200' cmt plug across 13 3/8" shoe up to 250'.
- 5. POOH w/ tbg. WOC 4 hrs. RIH & tag cmt plug @ 250'. POOH.
- 6. ND 3OP. Spot 10 sx surface plug. RD Service Co. ND WH. Cut off 9 5/8" csg. Weld on plate & dry-hole marker. RD PU.
- 7. Rip & re-seed location.

Note: Plug & abandonment procedures were discussed & OK'd w/ NMOCD rep. Tim Gum from Artesia office.