

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Peter well Servicing Co.	8. Farm or Lease Name Tom Lee
3. Address of Operator Box 1772, Hobbs, New Mexico 88240	9. Well No. I
4. Location of Well UNIT LETTER C, 1230 FEET FROM THE N LINE AND 1900 FEET FROM THE S LINE, SECTION 21, TOWNSHIP 22-S, RANGE 27-E, N.M.P.M.	10. Field and Pool, or Wildcat Aye-Selaware
15. Elevation (Show whether DF, RT, GR, etc.) 3552 M	12. County Lddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up
2. Run tubing to 3260'
3. Set 100' plug - 40 sx. cement
4. Pull on 9 5/8 and cut off at free point
5. Pull 9 5/8 and set 100' plug at cut off (40 sx.)
6. Set 100' plug & 310-410 (100 sx.)
7. Set 10' sx. plug, surface
8. Permission not to install dry hole marker at Tom Lee owns surface and the minerals. Well is in middle of his farm, acreage.
9. Clean up location and move off.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gray Baker

TITLE President

DATE 11/1/76

APPROVED BY W. A. Grasset

TITLE SUPERVISOR, DISTRICT II

DATE NOV 9 1976

CONDITIONS OF APPROVAL, IF ANY:

Intervals between plugs filled upward

Notify N.M.O.C.C. in sufficient time to witness

Shelton