

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Copy to SF
Form approved.
Budget Bureau No. 42-R1425.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

RECEIVED
MAR 30 1977

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Howard Boatright Co., Inc.

3. ADDRESS OF OPERATOR
811 First National Bank Building, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Unit G - 2003 FNL & 1836 FEL
Sec. 14, T-23-S, R-24-E

5. ELEVATIONS (Show whether DE, RE, OR, etc.)
N/A

5. LEASE DESIGNATION AND SERIAL NO.
NM 0303836

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Unit #1

8. FARM OR LEASE NAME
Smith Federal Co.

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Rock Tank

11. SEC., T., R., M., OR BLS. AND SURVEY OR AREA
Sec. 14, T-23-S, R-24-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	REPAIR OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETION	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANN	(Other)	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
(Other)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Proposed plugging procedure.

Set CIBP @ 9500' and cap w/35' cement. Determine free point of 5-1/2" casing. Cut and pull 5-1/2" casing out of hole. Spot a 150' plug in and out of 5-1/2" casing stub. Spot a 150' plug from 6450' to 6300'. Spot a 100' plug from 4600' to 4500'. Spot a 100' plug from 2850' to 2750'. Place a 50' plug in top of surface. Clean location and install Dry Hole marker.

RECEIVED

MAR 29 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE President DATE 3-23-77

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 28 1977
[Signature]
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side