	9-331		'NITED ST	ATES	SUBMIT IN	PLICATE*		a approved. get Bureau No. 42
(Ma)	y 1963)	DEPAR	ENT OF TI		(Other inst:	IN OR TE-	5. LEASE DESI	IGNATION AND BERI
			GEOLOGICAL	SURVEY			NM 029	
			TICES AND				6. IF INDIAN,	ALLOTTES OR TRIE
	(Do not use this fo	orm for pro Use "APPL	posals to drill or to ICATION FOR PERM	deepen or plug t iIT—" for such p	back to a different rese roposals.)	rvoir.		
1.					·····	···	7. UNIT AGRES	MENT NAME
,	WELL GAS WELL	X OTHER			RECEIV	<u>ED</u>	<u> </u>	
2.	NAME OF OPERATOR						8. FARM OR L	Federal
8.	Jake L. Hamo	n		<u> </u>		72	9. WELL NO.	rederal
	908 Vaughn B	uilding	, Midland, T	exas 7970	1		1	· · ·
1	LOCATION OF WELL (Re See also space 17 below	port location v.)	n clearly and in account	rdance with any			1	POOL, OR WILDCA
	At surface 1650' FNI、&	2310' 1	WL of Sectio	n 23	ARTESIA, DEF		11. SEC., T., B	k (Upper Mo
	T-23-S, R-24			/11 2.5 9				23, T-23-S
							R-24-E,	NMPM
14.	PERMIT NO.			(Show whether DF				E PARISH 18. ST.
				GR & 390			Eddy	New 1
16.			•••	To Indicate N	Nature of Notice, R	• •	· · · ·	e Britania Ngalana
	NC	TICE OF IN	TENTION TO:			SUBSEQ!	UENT REPORT OF	
	TEST WATER SHUT-OFT	·	PULL OB ALTER CAR		WATER SHUT-OF		-	PAIRING WELL
	FRACTURE TREAT Shoot or acidize		MULTIPLE COMPLET ABANDON*	re	FRACTURE TREA BELOOTING OR A			TERING CABING
	REPAIR WELL		CHANGE PLANS		(Other) Sett	ting 4-1	72" Produ	ction Car
					(Norm: R	eport_results	of multiple con	mpletion on Well ad Log form.)
	(Other)				I Completio			
17. 1	DESCRIBE PROPOSED OR (proposed work. If	COMPLETED (well is dire	OPERATIONS (Clearly s ctionally drilled, give	state all pertinen subsurface loca	i Completion t details, and give per tions and measured and	tipent dates.	including estin	nated date of star 1 markers and sor
	DESCRIBE PROPOSED OR of proposed work. If nent to this work.) *	well 18 dire	ctionally drilled, give	SUDSUFIACE IOCA	Completion t details, and give ber	tipent dates.	including estin	i markers and soi
17. 1	DESCRIBE PROPOSED OR of proposed work. If nent to this work.) *	well 18 dire	DPERATIONS (Clearly a ctionally drilled, give	SUDSUFIACE IOCA	Completion t details, and give ber	tipent dates.	including estin	i markers and soi
1.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7	/8" hol	e to 10,350	K.B.	Completion t details, and give per tions and measured and	tinent dates, d true vertic	including estin al depths for al	
1.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts	/8" hol	e to 10,350' -1/2" 11.6#,	K.B. N80 & J55	Completion t details, and give ber	tinent dates, d true vertic Casing	at 10,350	al articles (K.B.
1. 2.	DESCRIBE PROPOSED OR proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi	<pre>/8" hol . of 4- th 300</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla	K.B. N80 & J55 ass H Cemen	casing. Set	casing Plug do	at 10,350 wn at 11:	al and the moltourian lo alter the second se
1. 2.	DESCRIBE PROPOSED OR O proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera	/8" hol . of 4- th 300 ture Su	e to 10,350' -1/2" 11.6#, sacks of Cla	K.B. N80 & J55 ass H Cemen	t details, and give per tions and measured and	casing Plug do	at 10,350 wn at 11:	al and the moltourian lo alter the second se
1. 2.	DESCRIBE PROPOSED OR proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi	/8" hol . of 4- th 300 ture Su	e to 10,350' -1/2" 11.6#, sacks of Cla	K.B. N80 & J55 ass H Cemen	casing. Set	casing Plug do	at 10,350 wn at 11:	al and the moltourian lo alter the second se
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te	<pre>/8" ho] . of 4- th 300 ture Su 0 K.B. sted 4-</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla rvey at 9:00	K.B. N80 & J55 Iss H Cemer A.M. 10- to 2500ps:	casing. Set tors and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre	casing Plug do cement	at 10,350 wn at 11: at 9140'	al area of the mining of the m
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te	<pre>/8" ho] . of 4- th 300 ture Su 0 K.B. sted 4-</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00	K.B. N80 & J55 Iss H Cemer A.M. 10- to 2500ps:	casing. Set tors and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre	casing Plug do cement	at 10,350 wn at 11: at 9140'	al area of the mining of the m
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p	<pre>/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed	K.B. N80 & J55 Iss H Cemer A.M. 10- to 2500ps 1 10:00 A.1	casing. Set tions and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre M. 10-13-72.	casing Plug do cement	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2-	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed	K.B. N80 & J55 Iss H Cemer A.M. 10- to 2500ps: 1 10:00 A.1 and packet	casing. Set tions and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. F	casing Plug do cement	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2-	e to 10,350' -1/2" 11.6#, sacks of Cla ervey at 9:00 -1/2" casing c. Completed -3/8" tubing	K.B. N80 & J55 ass H Cemer A.M. 10- to 2500ps 1 10:00 A.1 and packet 9:15 A.M	casing. Set tions and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2-	e to 10,350' -1/2" 11.6#, sacks of Cla ervey at 9:00 -1/2" casing c. Completed -3/8" tubing	K.B. N80 & J55 ass H Cemer A.M. 10- to 2500ps 1 10:00 A.1 and packet 9:15 A.M	casing. Set tions and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. F	casing Plug do cement essure f	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
L. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2-	e to 10,350' -1/2" 11.6#, sacks of Cla ervey at 9:00 -1/2" casing c. Completed -3/8" tubing	K.B. N80 & J55 Iss H Cemer A.M. 10- to 2500ps 1 10:00 A.1 and packer 9:15 A.M	casing. Set tions and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2-	e to 10,350' -1/2" 11.6#, sacks of Cla ervey at 9:00 -1/2" casing c. Completed -3/8" tubing	K.B. N80 & J55 Iss H Cemer A.M. 10- to 2500ps 1 10:00 A.1 and packer 9:15 A.M	casing. Set it details, and give per shore and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2-	e to 10,350' -1/2" 11.6#, sacks of Cla ervey at 9:00 -1/2" casing c. Completed -3/8" tubing	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 10:00 A. and packer 9:15 A.M	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2-	e to 10,350' -1/2" 11.6#, sacks of Cla ervey at 9:00 -1/2" casing c. Completed -3/8" tubing	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 10:00 A. and packer 9:15 A.M	casing. Set it details, and give per shore and measured and casing. Set nt by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3. 4.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2- change	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed -3/8" tubing c. Completed	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 10:00 A.1 and packet 9:15 A.M 19:15 A.M 0 1.5.6 ABTE	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11: at 9140'	ral and the minimum of the action of the minimum of
1. 2. 3. 4. 5.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te no pressure te	/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2- change	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed -3/8" tubing c. Completed	K.B. N80 & J55 Iss H Cemer A.M. 10- to 2500ps 1 10:00 A.1 and packer 9:15 A.M 9:15 A.M	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn.at.10,350 wn.at.11; at.30,40' at.30,40' at.30,40' source source of a star source of a star source of a star for a star	ral and the minimum of the action of the minimum of
1. 2. 3. 4. 5.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te no pressure I hereby certify that t	<pre>/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2- change the foregola</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed -3/8" tubing c. Completed	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 10:00 A. and packer 9:15 A.M 12:00 U.S.C ARTE	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 30 min al depths for al at 10,350 wn at 30,350 wn at 30,350 wn at 30,550 at 30,450 at 30,450	ral and the minimum 10. The set of the set of
1. 2. 3. 4. 5.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te no pressure te no pressure te signed	<pre>/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2- change the foregola</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed -3/8" tubing c. Completed	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 1 10:00 A.1 and packer 9:15 A.M 0 U.S.C ARTE TITLE PO	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11, 30,457 wn at 11, 4,557 wn at 11, 30,457 sure for sure for at 30,457 at 30,457 at 30,457 at 30,457 at 1,570 at 30,457 at 30,457	ral and the minimum 10. The set of the set of
1. 2. 3. 4. 5.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te no pressure I hereby certify that t	<pre>/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2- change the foregoin</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed -3/8" tubing c. Completed -3/8" tubing c. Completed	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 10:00 A. and packer 9:15 A.M 12:00 U.S.C ARTE	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn.at.10,350 wn.at.11; at.30,40' at.30,40' at.30,40' source source of a star source of a star source of a star for a star	ral and the minimum 10. The set of the set of
1. 2. 3. 4. 5.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te no pressure te no pressure (This space for Feder	<pre>/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2- change the foregoin</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing c. Completed -3/8" tubing c. Completed -3/8" tubing c. Completed	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 1 10:00 A.1 and packer 9:15 A.M 0 U.S.C ARTE TITLE PO	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 10,350 wn at 11: at 30,451 states of a state of a	relation of the second of the
1. 2. 3. 4. 5.	DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Drilled 7-7 Ran 294 jts Cemented wi Ran Tempera at 10,275.0 Pressure te change in p Pressure te no pressure te no pressure (This space for Feder	<pre>/8" hol . of 4- th 300 ture Su 0 K.B. sted 4- ressure sted 2- change the foregoin</pre>	e to 10,350' -1/2" 11.6#, sacks of Cla arvey at 9:00 -1/2" casing - Completed -3/8" tubing - Completed -3/8" tubing - Completed -3/8" tubing - Completed -3/8" tubing - Completed -3/8" tubing - Completed 	K.B. N80 & J55 ISS H Cemer A.M. 10- to 2500ps 10:00 A. and packer 9:15 A.M 12:00 U.S.C ARTE TITLE	casing. Set it details, and give per kions and measured and by HOWCO. 9-72. Top of i and held pre M. 10-13-72. r to 4000#. H . 10-13-72.	casing Plug do cement essure f	at 10,350 wn at 11, 30,457 wn at 11, 4,557 wn at 11, 30,457 sure for at 30,457 at 30,457 at 30,457 at 30,457 at 10,350 wn at 11, 30,457 at 30,457 at 30,457	ral and the minimum 10 D. Second and the providence of the second provi