at end of test. Control values operated as indicated on closing unit manifold at end of test. Bop extentions were not hooked up - rig nippling up. No test desired to top of casing using packer, nor to the lower kelly cock, or to the drill pipe safety value.

VELLOW JACKET TOOLS AND SERVICES, INC.ODESSA, TEXASTest made by A. C. ScottI I Light