Form 9-331 (May 1963)		ENDEL ROPOSA			1 I	_	-
	DEPAF	TMENT OF TH		SUBMIT IN TRIPLA. (Otner instruction verse side)		Form approved Budget Bureau EASE DESIGNATION A 0479142	No. 42-R1424.
		GEOLOGICAL	T	RECEIT		· INDIAN, ALLOTTEE	OR TRIBE NAME
(Do not us	e this form for pr Use "APPI	OTICES AND R oposals to drill or to d LICATION FOR PERMI	eepen or plug back T-" for such prop	to a different regervoir. osals.) DE	NET	-	
	AB X OTHE	1	<u>. 13 : </u>	U.S. GEULUGICAL S	EXICO 7. U	NIT AGREEMENT NAS	12
2. NAME OF OPERA		/	····	U.S. GEOLOGICAL S ARTESIA, NEW M	8. 7	James-E	C
3. ADDRESS OF OPI	ERATOR	<u>,, , , , , , , , , , , , , , , , , , ,</u>	·····	· · · · · · · · · · · · · · · · · · ·		ELL NO.	· · · · · · · · · · · · · · · · · · ·
Room 806	, Phillips	Bldg., Odessa	, Texas 797	/61	D 10	1 FIELD AND POOL, OR	WILDCAT
4. LOCATION OF WI See also space 3 At surface	17 below i	it G) 1980' F		the refunder the way to the	i	in Lake -Moi	
	(0.			NEC 6 1977	7 11.	SEC., T., R., M., OR BI SURVEY OR AREA	K. AND
					11	, 22 - 5, 30-1	3
14. PERMIT NO. Or. approved 10-		DOSAL	Show whether DF, RT 1 Gr. 32201	DF, 3221 RKB	Ξ	COUNTY OR PARISH	13. STATE New Mexic
16.				ure of Notice, Report,	, or Other	Data	
	NOTICE OF IN	TENTION TO:	1	8	UBSEQUENT R	EPORT OF:	
TEST WATER S	HUT-OFF	PULL OB ALTER CAS	NG	WATER SHUT-OFF		REPAIRING W	
FRACTURE TRE.	AT	MULTIPLE COMPLETI		FRACTURE TREATMENT		ALTERING CAN	
SHOOT OR ACID Repair well		ABANDON* Change plans	x	SHOOTING OR ACIDIZIN	G []	ABANDONMEN	
	ndon Morrov	v gas zone onl	v	(NOTE : Report)	results of mu ecompletion 1	ltiple completion o deport and Log form	n Well
	SED OR COMPLETED rk. If well is dir	and a series (Clearly at	ate all nortinest d	etails, and give pertinent s and measured and true	dates, includ vertical dept	ing estimated date hs for all markers	of starting any and zones perti-
This anended between T. H	procedure arold McLem	to abandon Mo nore/Joe G. La	rrow gas zo ra on Decan	one only confirm aber 2, 1977.	s telep	hon e c onvers	sation
MI&RU D Pulled	2 3/8" Stra	awn oil zone t at 109631 and	ubing. Unab pulled tbg D-5 dual pa	rawn zone tubin ole to pull 2 7/ g. Cut 2 7/8" tu acker from ll,00	8" Morr bing at	ow gas zone 11,264", p	ulled 2 7/3
Cut 2 7 tubing tubing unlatch Baker F PROPOSE	from 11,264 string fish tbg from H packer.	n at 11,264 ¹ . Baker F packer BP to appro xim	at 13,2001	overshot and la . Ran free poi 201, set, and spo	tched of nt, cut	nto tbg fish 2 7/8" tub:	n, unable f ing above
Cut 2 7 tubing tubing unlatch Baker F <u>PROPOSE</u> abandon Will re	from 11,264 string fish tbg from H packer. to run CIH Morrow gas -run Strawn	n at 11,264 ¹ . Baker F packer BP to approxim s zone. n oil zone tub	at 13,2001 ately 13,12 ing string	. Ran free poi	nt, cut nt, cut t 20 fe product:	nto tbg fish 2 7/8" tub: et cement or	n, unable ing above n top of B
Cut 2 7 tubing tubing unlatch Baker F <u>PROPOSE</u> abandon Will re Oil poo Series	from 11,264 string fish tbg from H packer. to run CIH Morrow gas -run Strawn 1 with Morr 900 BOP, 30	h at 11,264 ¹ . Baker F packer BP to approxim s zone. h oil zone tub row gas zone a	at 13,200 ately 13,12 ing string bandoned be	. Ran free poi 201, set, and spo and restore to	nt, cut nt, cut t 20 fe product	nto tbg fish 2 7/8" tub: et cement on ion in Cabin	n, unable ing above n top of B n Lake Str
Cut 2 7 tubing tubing unlatch Baker F <u>PROPOSE</u> abandon Will re Oil poo Series 18. I bereburgerith SIGNED	from 11,264 string fish tbg from H packer. to run CIH Morrow gas -run Strawn 1 with Morr 900 BOP, 30	h at 11,264 ¹ . Baker F packer BP to approxim s zone. h oil zone tub row gas zone a 2000# WP, doubl ms is true and correct T. C. Rodgers	at 13,200 ately 13,12 ing string bandoned be	. Ran free poi 201, set, and spo and restore to 210w CIBP and ce	and one	nto tbg fish 2 7/8" tub: et cement on ion in Cabin	n, unable ing above n top of B n Lake Stra rans.

٠

*See Instructions on Reverse Side