Form 3 160 (June 1990	C 35 MI SUNDRY NOTICES	TED STATES NT OF THE INTERIOR LAND MANAGEMENT AND REPORTS ON WEL rill or to deepen or reentry to R PERMIT—" for such propo	a a different reserv	NM OIL CONS COMMISSION Drawer DD Artesia, NM 88210 FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM-0479142 6. If Indian, Allottee or Tribe Name
<u>}</u>		T IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of				
X Well Gas Other			8. Well Name and No.	
2. Name of Operator Phillips Petroleum Company			James E Fed No. 1 9. API Well No.	
3. Address and Telephone No.			30-015-20996	
4001 Penbrook Street, Odessa, TX 79762			10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit G, 1980' FNL & 1980' FEL of Section 11, T-22-S,			Cabin Lake (Delaware	
R-3	0 – E			Eddy, NM
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT			PORT, OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION		
	X Notice of Intent	Abandonment		Change of Plans
		Recompletion		New Construction
	Subsequent Report	Plugging Back		Water Shut-Off
	Final Abandonment Notice	Altering Casing	1	Conversion to Injection
		X Other Tem	porarily Aba	
				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
giv 1.	ve subsurface locations and measured and true vertion MI&RU DDU. ND well	ical depths for all markers and zones pertin .head. NU Class 2	BOPE.	starting any proposed work. If well is directionally drille
2.	RIH w/slick line & tag fill over RBP at ± 5800 '. Clean out if necessary Retrieve RBP at ± 5800 '. COOH with $2-7/8$ " tubing and RBP. GIH w/5-1/2" CIBP on $2-7/8$ " tubing. Set CIBP at ± 5600 '. Test $5-1/2$ "			
3.	casing & CIBP to 500 psi for 30 minutes.			
4.	COOH Laying down 2-7 DDU.			OP. NU top flange. RD
	y certify that the foregoing is true and correct			
Signed	Am Dand.	Title Supv.Regu	DLEUM ENGN	915)_368=1488

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be considered for Temporary Abandonment (TA) approval for 12 months provided the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.