

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

O. C. D.
ARTESIA OFFICE

WELL API NO. 30 015 21007
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. NM 0515150
7. Lease Name or Unit Agreement Name Westfall A COM
8. Well No. 1
9. Pool name or Wildcat Carlsbad, South (Morrow)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3170.07' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator Southwest Royalties, Inc. ✓
3. Address of Operator c/o P.O. Box 953, Midland, Texas 79702
4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 5 Township 23-S Range 27-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: to be P & A within 90 days ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Detail: 13 3/8" @ 392', 450 sx-circulated, 8 5/8" @ 5535', 1550 sx-top cmt-1630',
5 1/2" @ 12,050', 800 sx-top cmt-8060'.

Plugging Procedure:

- 1) Set CIBP @ 10,800 w/20' cmt-top (Morrow-11,125', Atoka-10978')
- 2) Set CIBP @ 8800' w/20' cmt-top (Wolfcamp-8840')
- 3) Set 70 sx plug from 5300-5600' (cut-5450', shoe-5535', Bone Springs-5350')
- 4) Set 30 sx plug from 2950-3050' (Wolfcamp-8840')
- 5) Set 30 sx plug from 1845-1945' (Delaware-1895')
- 6) Set 30 sx plug from 1460-1560' (Base Salt-1510')
- 7) Set 30 sx plug from 340-450' (Top salt-400', shoe-392')
- 8) Set 10 sx surface plug.

* Gel Between
All Plugs - Note
on attached sheet

Intend to pull 5 1/2" casing @ approx. 5450'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Agent DATE 10-9-91
TYPE OR PRINT NAME Ann E. Ritchie TELEPHONE NO 915 684-6381

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 11/7/91
CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging

RECEIVED

OCT 10 1991

STATE OF CALIFORNIA