

pressured to 1500# at end of test. Control valves operated as indicated on closing unit manifold at end of test. Bop extentions were hooked up - rig coming out of hole. No test desired to top of casing using packer, nor to the upper kelly cock, or to the lower kelly cock (not in rig inventory at time of test).

YELLOW JACKET TOOLS AND SERVICES, INC.

ODESSA, TEXAS

Test made by R. E. Daniel *R. E. Daniel*