

DEV-1-98 10:24 AM UCD TRIST II

FAX NO. 505740 0

P. 3

Submit 3 Copies
to Appropriate
District OfficeState of New Mexico
Energy, Minerals and Natural Resources DepartmentForm C-101
Revised 1-1-89DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-0-15-21169
3. Indicate Type of Lease STATE ☒ PER ☐
6. State Oil & Gas Lease No. KO 4403
7. Lease Name or Unit Agreement Name State L-4325 Com #1
8. Well No. 001
9. Pool name or Wildcat Black River Atoka, North

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator Fredonia Resources, Inc.
3. Address of Operator 3355 W. Alabama, Suite 950, Houston, TX 77098
4. Well Location Well Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>02</u> Township <u>24S</u> Range <u>26E</u> NMPM <u>Eddy</u> County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) 10 SXS @ Surface
- 2) 100' cmt plug 490' - 350' tag
- 3) 100' cmt plug 50' in & out CS6 stub tag
- 4) cut & plug 85/8" CS6 1375' +/- after Freeport 02/14 temp survey
- 5) 100' cmt plug 5496' - 5396' tag
- 6) 25' cmt plug 7035'
- 7) 25' cmt plug 8830' - may be combined w/ stub plug
- 8) 100' cmt plug 50' in & 50' out of 5/2 stub - tag
- 9) Freeport 4 cut 5/2 CS6
- 10) Circulate brine gel to surface or cut CS6 off point
- 11) CIBP w/ 35' cmt set 10,506' OR 25 SXS cmt plug 10,406 - 10,506 tag

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken Chamberlain TITLE operatorDATE 2/13/01

TYPE OR PRINT NAME

Ken Chamberlain

TELEPHONE NO

903 2974800

(This space for State Use)

APPROVED BY Michael G. WellfieldTITLE Field Rep. IIDATE 3/6/2001

CONDITIONS OF APPROVAL, IF ANY:

* Notific N.M.O.C.D. To witness Plugging Operations.