

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Henri Grandi
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated Wildcat
12. County Cady

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEEPER ZONE. SEE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Apaxco, Inc.
3. Address of Operator 1121 First Place Tulsa, Oklahoma 74103
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>1800</u> FEET FROM THE <u>South</u> LINE, SECTION <u>26</u> TOWNSHIP <u>22S</u> RANGE <u>27E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3084.7 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PLUG OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-8-75 Shut down
11-9-75 Shut down
11-10-75 Rec. 1500' fluid, no gas or oil, all water
11-13-75 Shot 4 1/2" casing at 2175' and pulled. Shot 9-5/8" at 1200' could not pull. Shot at 1036' and pulled. Set 60 ex. cement plug 988' to 1088'. Filled hole with brine water to 460' and set 60 ex. cement plug 360' to 460'. Bottom 12-3/4" surface casing. Set 10 ex. cement plug 3' to 15'. Set dry hole marker and welded on cap. Well P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Raymond R. Sonu TITLE Division Production Manager DATE November 13, 1975

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: