

of test.

NO VISIBLE LEAK. PRESSURE LEVELING OUT TOWARDS APPROXIMATELY 2900#.

---

A delay was observed to operation of blowout control equipment at the conclusion of testing - closing lines leaked (repaired as needed) and closing lines to Hydril crossed (corrected as needed). Closures were made using closing unit pump only to the observed pressure of 2300# for test to ram type bops and 1500# for test to Hydril. Accumulators were pressured to 1500# at end of test. Control valves operated as indicated on closing unit manifold at end of test. Bop extentions were not hooked up - rig nipping up. No test desired to top of casing using packer, nor to the upper kelly cock (not in rig inventory at time of test), to the lower kelly cock (not in rig inventory at time of test), or to the drill pipe safety valve (not in rig inventory at time of test).

YELLOW JACKET TOOLS AND SERVICES, INC.

ODESSA, TEXAS

Test made by Gary Hodges

*Gary Hodges*