DEPARTMENT OF THE INTERIOR ARTESIA, C	
GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use form 9-331-C for such proposals.) 1. oil gas well other Injection Well 2. NAME OF OPERATOR <u>Amoco Production Company</u> 3. ADDRESS OF OPERATOR <u>P. O. Box 68, Hobbs, New Mexico 88240</u> 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1980' FNL X 1980' FEL	 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Old Indian Draw Unit 9. WELL NO. 5 10. FIELD OR WILDCAT NAME Indian Draw Delaware 11. SEC., T., R., M., OR BLK. AND SURVEY O AREA 18-22-28
AT SUBFACE: 1500 THE A 1500 THE A 1500 THE AT TOP PROD. INTERVAL: (Unit G, SW/4, NE/4 AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES	12. COUNTY OR PARISH 13. STATE Eddy NM 14. API NO. 15. ELEVATIONS (SECONDER, AND WE 3081' SCL COMMENT (NOTE: Report results of pulling commention or zor change on Form 3330
 ABANDON• (other) CONVERT to injection 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Propose to convert to a injection per the fol Move in service unit and POH. RIH with packe Load backside with 2% KCL fresh water. Run a PBTD (3412') - 3100'. Check for a channel do 	lowing: n and tubing. Set packer ±3100' pump in tracer survey from

(3312'-3340'). If a channel is found, release packer and POH. RIH with cement retainer for 5-1/2" casing. Set retainer at $\pm 3225'$. Cement squeeze the interval 3278'-3295' with 100 sx of class C neat cement. WOC 24 hrs. RIH with bit and drill out cement, retainer, and cement. Pressure test squeeze to 500 psi for 30 min. Clean out well to PBTD (3412') and circulate hole clean. RIH with casing gun and perforate the intervals 3278'-3290' and 3232'-3250' with 4 DPJSPF at 90° or 120° phasing. RIH with RBP, re-treiving head. packer winkunloader, and tubing. Set RBP at ±3300' Raise up (over O+6-BLM, R 1-HOU, R. E. Oqden, Rm 21.150 1-F. J.Nash, HOU Rm 4.206 1-CMH Subsurface Safety Valve: Manu. and Type _ Set @ _ _ Ft. 18. I hereby sertify that the foregoing is true and correct _____Admin. Analyst 12-2-83 SIGNED TRAN ng DATE APPROVED (This space for Federal or State office use)

APPROVED (Orig. Sgd.) PETER W. CHESTE DATE CONDITIONS OF APPROVAL, IF ANY: SUP YOT TO LIKE

DEC 9 1983

See	Instructions	on	Reverse	S!.

and set packer at $\pm 3265'$. Acidize the interval 3278' - 3290' with 1200 gal of 15% LSTNE HCL acid with additives. Flush acid to bottom perfs with 2% KCL fresh water. Release packer, drop down, and latch onto RBP set at 3300'. Raise up and set RBP at $\pm 3270'$. Pull up 10' and set packer. Test RBP at 500 psi. Release packer and set at 3150'. Load backside with 2% KCL fresh water. Acidize the intervals 3232' - 3250' with 1800 gal of 15% LSTNE HCL acid with additives. Flush acid to bottom perfs with 2% KCL water. Release packer and drop down. Latch onto RBP at 3270'. Reset RBP at $\pm 3330'$ and set packer at $\pm 3150'$. Swab to recover load. Release packer, drop down, and latch onto RBP. POH. RIH with injection packer and 2-3/8" plastic coated tubing. Set packer at $\pm 3140'$. Displace casing with packer fluid. Move out service unit and commence injection at a maximum of 300 psi surface injection pressure.

* This work was approved by NMOCD Administrative Order No. WFX-520.

0