

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
311 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY

3. Address and Telephone No.

P. O. Box 1030
Roswell, New Mexico 88202-1030 505-622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FSL & 330' FEL
Section 13-23S-29E

5. Lease Designation and Serial No.

NM-17589

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Nash Unit

8. Well Name and No.

Nash Unit #5

9. API Well No.

30-015-21800

10. Field and Pool, or Exploratory Area

Nash Draw Brushy Canyon

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION



Notice of Intent



Abandonment



Change of Plans



Subsequent Report



Recompletion



New Construction



Final Abandonment Notice



Plugging Back



Non-Routine Fracturing



Casing Repair



Water Shut-Off



Altering Casing



Conversion to Injection



OTHER



Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

01/10/00: MI.
01/11/00: RU. TOH with rods and pump. NU BOP. TOH with tubing.
01/12/00: Perf 16 .42 holes at 6786'-6809' and 9 .42 holes at 6012'-6020'.
01/13/00: Acidize perfs at 6012'-6020' with 1000 gallons acid. Clean out paraffin. Swab test.
01/25/00: Perf 7 .42 holes at 5744'-5749'.
01/26/00: Acidize with 900 gallons acid. Swab test and evaluate.
01/31/00: Frac with 4500 gallons gel and 3000# 16/30 RC sand. Swab test and evaluate.
02/04/00: Perf 8 .42 holes at 5479'-5486'.
02/05/00: Acidize with 1500 gallons acid. Swab test and evaluate.
02/07/00: Frac with 3000# 16/30 RC sand and 4400 gallons gel.
02/10/00: TOH with tools. TIH with production string. ND BOP. Flange up wellhead. TIH with pump and rods. Hang on. Start pumping. Release rig. RDMO. Place on production.

14. I hereby certify that the foregoing is true and correct.

Signed

David F. Glass

Title: Production Records Manager

Date: 3/14/2000

(This space for Federal or State office use)

Approved by

Title: OREGON (SGD) DAVID F. GLASS

Date

Conditions of approval, if any:

