# STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| , <u> </u>            | 1 |  |
|-----------------------|---|--|
| we ar corice sectives | 1 |  |
| DISTRIBUTION          |   |  |
| SANTA FE              |   |  |
| FILE                  |   |  |
| U.S.O.S.              |   |  |
| LAND OFFICE           |   |  |
| OFFRATOR              | 1 |  |

|  | VATION DIVISION   |   |
|--|---|---|
| DISTRIBUTION P. O.   | BOX 2088 RECEIVED   | Form C-103  |
| SANTA FE SANTA FE N  | NEW MEXICO 87501  | Revised 10-1-7  |
| FILE   | V24 W(2)(100 07301  | La Indiada Tuez el Lene   |
| U.S.O.S.   | JUN 17 1980   | Sa. Indicate Type of Lease  |
| LAND OFFICE  | <b>50</b> 1 1 1000  | State X Foo   |
| OPERATOR   | O. C. D.  | 5. State Oil & Gas Lease No. L-776  |
| SUNDRY NOTICES AND REPORTS   | ON WELLS ARTESIA, OFFICE  |   |
| IDO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR F   | PLUG BACK TO A DIFFERENT RESERVOIR.<br>OR SUCH PROPOSALS.)  |   |
| OIL GAS OTHER-   |   | 7, Unit Agreement Name  |
| 2. Name of Operator  |   | 8, Farm or Lease Name   |
| GULF OIL CORPORATION   |   | Eddy "GN" State Com   |
| , Address of Operator  |   | 9. Well No.   |
| P. O. Box 670, Hobbs, NM 88240   |   | 1   |
| Location of Well   |   | 10. Field and Pool, or Wildcat  |
|  |   | 77 - 1  |
| UNIT LETTER G . · 1880 FEET FROM THE NO  | rth LINE AND 1980 FEET FR   | Undes. Strawn   |
|  |   |   |
| THE East LINE, SECTION 28 TOWNSHIP   | 23S RANGE 26E NMP   |   |
| 15. Elevation (Show wh   | ether DF, RT, GR, etc.)   | 12. County  |
|  | 3325 GL   | Eddy  |
|  |   |   |
| Check Appropriate Box To Indica  | ite Nature of Notice, Report or C   | Other Data  |
| NOTICE OF INTENTION TO:  | SUBSEQUE  | NT REPORT OF:   |
|  |   |   |
| PERFORM REMEDIAL WORK PLUG AND ABANDON   | X REMEDIAL WORK   | ALTERING CASING   |
| TEMPORARILY ASANDON  | COMMENCE DRILLING OPNS.   | PLUG AND ABANDONMENT  |
| PULL OR ALTER CASING CHANGE PLANS  | CASING TEST AND CEMENT JOB  | Lan.  |
|  |   |   |
| POLL ON ACTER CASING   |   |   |
| _  | OTHER   |   |
| OTHER  |   |   |
| OTHER  | RAHTO   | ne estimated date of starting any propose   |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  | OTHER   |   |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  | OTHER   |   |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1703.  Kill well if necessary with 8.6# GKF. POH   | other   | t CIBP @ 10,400'. Circu-  |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP 1  | other other at details, and give pertinent dates, including with packer & tubing. Se with 35° cement to test to                     | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack  |
| North Proposed or Completed Operations (Clearly state all pertines work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP to cement plug on top of 5" liner. POH with  | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on li   | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"   |
| North Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set  | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| North Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set  | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| Notes The Preposed of Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur            | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| Notes The Preposed of Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur            | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP coment plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur           | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on 1i cement plugs from 4550' to                            | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The Proposed of Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur location.        | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on li cement plugs from 4550' to rface plug. Place dry hold | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The Proposed of Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur location.        | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on li cement plugs from 4550' to rface plug. Place dry hold | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |
| The scribe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur location. | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on li cement plugs from 4550' to rface plug. Place dry hold | t CIBP @ 10,400'. Circu- 1000#. Put a 35 sack fe nipple. Cut 7-5/8" o 4650', 2675' to 2775, e marker; clean & clear |
| Tr. Describe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103.  Kill well if necessary with 8.6# GKF. POH late hole with abandonment mud. Cap CIBP to cement plug on top of 5" liner. POH with casing @ 4500' to pull 7-5/8" casing. Set 1957' to 2057', 240' to 340', and a 50' sur      | with packer & tubing. Se with 35' cement to test to 2-3/8" tubing. Well on li cement plugs from 4550' to rface plug. Place dry hold | t CIBP @ 10,400'. Circu-<br>1000#. Put a 35 sack<br>fe nipple. Cut 7-5/8"<br>o 4650', 2675' to 2775,                |

# STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| NO. 47 EGPIES RECEIVES | T        |   |
|------------------------|----------|---|
| DISTRIBUTION           | <u> </u> | · |
| SANTA PE               |          |   |
| FILE                   |          |   |
| U.\$.0.\$.             |          | - |
| LAND OFFICE            |          |   |
| OFFRATOR               |          |   |

ONDITIONS OF APPROVAL, IF ANYI

# OIL CONSERVATION DINEGENAD

| DISTRIBUTION                                      | Р. О. ВО   |   | Form C-103                                |
|---|--|---|---|
| SANTAPE   | SANTA FE, NEV  | V MEXICO 875 17 1980                      | Revised 19-1-78                           |
| V.S.O.S.  |  | JUN T ( 1300                              | Sa. Indicate Type of Lease                |
| LAND OFFICE                                       |  |   | State X Foo                               |
| OPERATOR  | •  | O. C. D.                                  | 5. State Oll & Gas Lease No.              |
| <u> </u>  |  | ARTESIA, OFFICE                           | L-776                                     |
| SUMPRI  | ANTICES AND DEDODITE ON  | WELLS                                     | mminimini                                 |
| IDO NOT USE THIS FORM FOR PROP                    | Y NOTICES AND REPORTS ON   | RACK TO A DIFFERENT RESERVOIR             |   |
| USE TAPPLICATIO                                   | ON FOR PERMIT -** IFORM C-101) FOR SU  | TH PROPOSALS.1                            | 7, Unit Agreement Name                    |
| . OIL CAS T                                       |  |   | 7. Only Agreement Name                    |
| weil weil X                                       | OTHER-   |   |   |
| Name of Operator                                  |  |   | 8. Farm or Lease Name                     |
| GULF OIL CORPORA                                  | TION   |   | Eddy "GN" State Com                       |
| Address of Operator                               |  |   | 9. Well No.                               |
| P. O. Box 670, H                                  | lobbs, NM 88240  |   | 1   |
| . Location of Well                                |  |   | 10. Field and Pool, or Wildcat            |
| UMIT LETTER G · 1                                 | 880 FEET FROM THE North  | LINE AND 1980 PEET PRO-                   | Undes. Strawn                             |
| VAII 621167                                       | The state of the s |   |   |
| East  | 2823S  | 26F                                       |   |
| THE LINE, SECTION                                 | TOWNSHIP 230   | MANGE ZOE NAPA                            |   |
|   | 15. Elevation (Show whether  | DF. RT. GR. etc.)                         | 12. County                                |
|   |  | 25' GL                                    |   |
|   | - <del></del>  |   | Eddy ()                                   |
| Check A   | ppropriate Box To Indicate N   | Nature of Notice, Report or Ot            | ther Data                                 |
| NOTICE OF IN                                      | FENTION TO:  | SUBSEQUEN                                 | T REPORT OF:                              |
| •   |  |   |   |
| PERFORM REMEDIAL WORK                             | PLUG AND ABANDON   | REMEDIAL WORK                             | ALTERING CASING                           |
| TEMPORARILY ABANDON                               |  | COMMENCE DRILLING OPNS                    | PLUG AND ABANDONMENT                      |
| PULL OF ALTER CASING                              | CHANGE PLANS   | CASING TEST AND CEMENT JOB                |   |
|   |  | OTHER                                     |   |
|   |  | OTHER                                     |   |
| OTHER   |  | •   |   |
| 7. Describe Proposed or Completed Ope             | rations (Clearly state all pertinent det   | ails, and give pertinent dates, including | g estimated date of starting any proposed |
| work) SEE RULE 1103.                              |  |   |   |
| Kill well if necessary                            | with 8.6# GKF. POH with  | th packer & tubing. Set                   | CIBP @ 10,400'. Circu-                    |
| late hole with abandon                            | ment mud. Cap CIBP with  | h 35° cement to test to                   | 1000#. Put a 35 sack                      |
| cement plug on top of                             | 5" liner. POH with 2-3   | /8" tubing. Well on life                  | e nipple. Cut 7-5/8"                      |
| casing @ 4500' to pull                            | 7-5/8" casing. Set cer   | ment plugs from 4550' to                  | 4650 2675 to 2775                         |
| 1957' to 2057' 240' to                            | $0.340^{\circ}$ and a $50^{\circ}$ surface   | ce plug. Place dry hole                   | marker: elean c elean                     |
| location.   | Jord , and a Jo Darra  | se plug. Trace day note                   | marker, clean & clear                     |
| 200002011,  |  |   |   |
|   |  |   |   |
|   |  |   |   |
|   |  |   | • .                                       |
|   |  |   |   |
| •   | •  |   | •   |
|   |  |   |   |
|   | •  |   |   |
|   |  |   |   |
|   |  |   |   |
|   |  |   |   |
|   | ·  |   | ,   |
|   |  |   | ·   |
|   |  |   |   |
|   |  |   |   |
| 8. I hereby certify that the information at       | ove is true and complete to the best c   | of my knowledge and belief.               |   |
| · - 1   |  |   |   |
| $\mathcal{A} \mathcal{A} \mathcal{A} \mathcal{A}$ | - 10   | Amon Engineer                             | 6-16-80                                   |
| IGHED . MES                                       | - 1. TITLE   | Area Engineer                             | DATE U- LU-OU                             |
|   |  |   |   |
|   |  |   |   |

# STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| 40, 07 COPIED RECEIVED |  |
|------------------------|--|
| DISTRIBUTION           |  |
| SANTA PE               |  |
| TILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OFERATOR               |  |

| NO. OF COPIES RECEIVED                   | OIL CONSERVATION DIVISION   |   |
|--|---|---|
| DISTRIBUTION                             | P. O. BOX 2088 RECEIVED   | Form C-103                                    |
| SANTAFE                                  | SANTA FE, NEW MEXICO 87501  | Revised 19-1-78                               |
| TILE                                     |   |   |
| U.S.G.S.                                 | JUN 17 <b>1980</b>  | Sa. Indicate Type of Leuse                    |
| LAND OFFICE                              | 3311 11 1333  | State X Foo                                   |
| OPERATOR                                 |   | 5. State Oil & Gas Lease No.                  |
| <u> </u>                                 | O. C. D.  | L-776   |
| SILIO                                    | ARTESIA, OFFICE   | mmmmmm-                                       |
| IDO MOT USE THIS FORM FOR PAC            | RY NOTICES AND REPORTS ON WELLS   |   |
| USE "APPLICAT                            | ION FOR PERMIT -" IFORM C-101) FOR SUCH PROPOSALS.)                             |   |
|  |   | 7. Unit Agreement Name                        |
| OIL GAS WELL X                           | OTHER-  |   |
| . Name of Operator                       |   | 8. Farm or Lease Name                         |
| · GULF OIL CORPOR                        | Δ ΤΤ ΛΝ   | Eddy "GN" State Com                           |
| , Address of Operator                    | ZII TOM   | 9. Well No.                                   |
|  | 11  | 9. Well 140.                                  |
|  | Hobbs, NM 88240   | 1   |
| . Location of Well                       |   | 10. Field and Pool, or Wildcat                |
| С .                                      | 1880 FEET FROM THE North LINE AND 1980 FEET                                     | Undes. Strawn                                 |
| UNIT LETTER                              | 1000 FEET FROM THE 1901 LIL LINE AND 1900 FEET                                  | TITITITITITITITITITITITITITITITITITITI        |
|  |   |   |
| THE East LINE, SECTION                   | ON 28 TOWNSHIP 23S RANCE 26E N  | MPM. (  |
|  |   |   |
|  | 15. Elevation (Show whether DF, RT, GR, etc.)                                   | 12. County                                    |
|  | 3325' GL  | Eddy  |
| <del>Tuminininini</del>                  |   |   |
| Check .                                  | Appropriate Box To Indicate Nature of Notice, Report or                         | Other Data                                    |
| NOTICE OF IN                             | NTENTION TO: SUBSEQU  | ENT REPORT OF:                                |
| •  |   |   |
|  | PLUG AND ABANDON X REMEDIAL WORK  |   |
| PERFORM REMEDIAL WORK                    | — I   | ALTERING CASING                               |
| TEMPORARILY ABANDON                      | COMMENCE DRILLING OPHS.   | . PLUG AND ABANDONMENT                        |
| PULL OR ALTER CASING                     | CHANGE PLANS CASING TEST AND CEMENT JOB   |   |
|  | OTHER   |   |
| OTHER                                    |   |   |
|  |   |   |
| 7. Describe Proposed of Completed Op     | perations (Clearly state all pertinent details, and give pertinent dates, incli | iding estimated date of starting any proposed |
| work) SEE RULE 1103.                     |   |   |
| Kill well if necessar                    | y with 8.6# GKF. POH with packer & tubing. S                                    | et CIBP @ 10.400'. Circu-                     |
|  | nment mud. Cap CIBP with 35 cement to test t                                    |   |
|  |   |   |
|  | 5" liner. POH with 2-3/8" tubing. Well on 1                                     |   |
| casing @ 4500' to pul                    | 1 7-5/8" casing. Set cement plugs from 4550'                                    | to 4650', 2675' to 2775,                      |
| 1957' to 2057', 240'                     | to 340°, and a 50° surface plug. Place dry ho                                   | le marker: clean & clear                      |
| location.                                | ,   |   |
| rocacion,                                |   |   |
|  |   | •   |
|  | •   |   |
|  |   |   |
|  |   | ·   |
|  | ,   |   |
|  |   | •   |
|  |   |   |
|  | ·   |   |
| •  |   |   |
|  |   | •   |
|  |   |   |
|  |   |   |
| ,  |   | •   |
|  |   |   |
|  |   |   |
|  |   |   |
| 8. I hereby certify that the information | shove is true and complete to the best of my knowledge and belief.              |   |
|  | <del>-</del>  |   |
| Vi Q Sila                                | 1   | 6 16 00                                       |
| ICHEO // O. NIKE                         | Area Engineer   | 6-16-80                                       |
|  | - <del>/ J </del>   |   |
|  |   |   |
|  |   |   |