

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. 4 COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

JIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-776

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Eddy "GN" State Com
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1880</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>23S</u> RANGE <u>26E</u> N.M.P.M.	10. Field and Pool, or Wildcat Undes. Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3325' GL	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

POH with production equipment. Set CIBP at 10,400', spot 10 sacks cement on top. Spot 35 sacks cement at 8643', cut 7-5/8" at 4500'; POH with casing. Spot 70 sack cement plug. Spot 85 sack plug at 2780', spot 85 sacks at 2050', spot 70 sacks cement at 340' and 15 sacks at surface. Install dry hole marker, clear and clean location. P&A complete 11-13-80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. P. R. R. TITLE Area Engineer DATE 11-17-80

APPROVED BY Mike Sturfield TITLE OIL AND GAS INSPECTOR DATE JAN 26 1981

CONDITIONS OF APPROVAL, IF ANY: