

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

OCT 18 1984

O. C. D.

ARTESIA OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator HCW Exploration, Inc.	8. Farm or Lease Name Ann Com.
3. Address of Operator P.O. Box 10585, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1655</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>24-S</u> RANGE <u>28-F</u> NMPM.	10. Field and Pool, or Wildcat Bone Springs, <u>MALAGA Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3022' KB	12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to begin plugging this well approximately October 24, 1984 as follows:

1. Pull rods & tbg.
2. Set CIBP @ 6250'. Dump 35' cement on top.
3. RIH w/tbg. Circulate mud laden 9.5 brine
4. Spot 100' cement plug @ 4100' - 4200' * min 25 sx plug
1400-2000 2100' - 2200' * " " " "
550-650 500' - 600' * " " " "
5. Set 10 sx plug @ surface.
6. Cut off wellhead & cap surface.
7. Weld marker joint on casing.
8. Move off all equipment.
9. Clean & level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Welch TITLE Production Superintendent DATE 10-17-84

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE OCT 26 1984

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging