STATE OF NEW MEXICO		RE	CEIVED BY		
ENERGY AND MINERALS DEPARTMEN	IT.				
	OIL CONSERVA	TION DIVISION	N 23 1834		
DISTAIRUTION	P. O. BO	C 2088	• •	Form C-103	
SANTA FE	SANTA FE, NEW		O. C. D.	Revised 10-1-7	
PILE UU	900100 E, NEW	. A	RTESIA, Sor-Inoreal	Type of Lette	
U.S.O.S.	· ·		State		
LAND OFFICE			L	6 Gas Lease No.	
OPERATOR				· · · · ·	
			LG-6	544 ******	
SUNDRY USE THIS FORM FOR PROP	NOTICES AND REPORTS ON	WELLS	·•·		
1. OIL CAS X	QTHER.		7, Unit Agr	cement Name	
2. Name of Operator			8. Farm or	8. Farm or Lease liame	
AMOCO PRODUCTION COMPANY			Stat	State IB Com	
1. Address of Operator	<u></u>		9. Well No.		
P. O. Box 68, Hobbs,	NM 88240		1 1		
4. Location of Well			10. Field o	nd Pool, or Wildcal	
N 6	N 660 South 1980		Balc	Baldridge Canyon	
UNIT LETTER	FEET FROM THE		FEET FROM	mmmm	
West	31 23 <b>-</b> S	25-E			
THE LINE, SECTION	JL	RANGE	<u> </u>		
	15. Elevation (Show whether 388.1' GL	DF, RT, GR, esc.)	l <sup>12.</sup> Éddy		
16. Charles A	ppropriate Box To Indicate N	ature of Nation Pop	art of Other Data		
NOTICE OF IN		•	SEQUENT REPORT	OF	
	5	000			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
F		COMMENCE DRILLING OPHS.		PLUG AND ABANDONMENT	
TEMPORARILY ABANDON	CHARGE PLANS	CASING TEST AND CEMENT J			
PULL OR ALTER CASING		OTHER	~ LJ	· _	
		VINCN		L_	
OTHER	[				
17. Describe Proposed or Completed Ope	erations (Clearly state all pertinent deta	ils, and give pertinent date	s, including estimated do	ite of starting any propose	
work) SEE RULE 1103.					
<b>D</b>	aufa and wonowf as follo	2.45.			

Propose to squeeze perfs and repert as tollows:
Mawa in convice unit and load well with FW with 2% KCL. Release packer, pull tubility,
packer and tailpipe. Log from 10400'-10700'. Run in hole with cement retainer and
packer and callpipe. Log from log actablish injection nate. Pump 75 sacks class H
set at 10410'. Test retainer and establish injection rate. Pump 75 sacks class H
cement with enough fluid loss additives to provide a waterloss of 100 cc's/30 min.
Ectablich low processing squeeze and sting out of retainer and reverse out dry excess
compart Dull tubing and wait on cement 24 hours. Urill out cement relativer and
cement to 10575'. Run in with and 1 stand of tubing. Set packer and pressure test
sugeeze to 1000 psi for 15 min. Pull tubing and packer. Log from 10,400'-10,700'.
sugeeze to 1000 psi for 15 min. Put tubing and packets Log with packer and tubing and
Perforated 10552'-10572' with 4 JSPF at 90° phasing. Run in with packer and tubing and
act nackaw at 10 5201. Swab and acidize with 2000 dals /-1/2% HUL dru duullives.
Deact packon at 10/80'+ Run nump tracer survey to determine it water zone is survey
in communication with caugezed zone Pull tubing and Dacker. Run in with tement
retainer and set at 10,530' with wireline. Run in tubing and test cement retainer.
retainer and set at 10,350 Will Wire inicitial C treatment at a max mate of 1.2 BPM on
Pump 10-20 bbl FW with 2% KCL. Pump injectrol G treatment at a max rate of 1-2 BPM or
max surface treating pressure of 2000 PSI as follows:
a) Pump 5000 gal of Injectrol G with activator
b) Dump 2 bblc of FW with 2% KCl
0+5-NMOCD,A 1-R. E. Ogden, HOU Rm. 21.150 1-F. J. Nash, HOU Rm. 4.206 1-PJS
13. I have by certify that the information above is true and complete to the best of my knowledge and belief.
10. I have by certify that the information above is true and complete to an a second sector.
Assist. Admin. Analyst 1-20-84
Assist. Admin. Analyst 1-20-84

Pienco Pietu & Sema	Assist. Admin. Analyst	1-2	0-84
APPERVED BY	Original Signed By Leslie A. Clements , Supervisor District II	"., <u>J</u> A	N 23 1984

- c) Pump 60 sacks class H neat cement.

d) Flush with 35 bbl of water with 2% KCL.
e) Sting out of retainer and reverse out excess cement. Spot 200 gals of 7-1/2% HCL with additives across the interval 10525'-10325'.

Swab 2000' and then pull tubing. Wait on cement and Injectrol 24 hours to set up. Perforate 10512'-10521' with 2 JSPF at 120° phasing. Run in as follows:

 a) 3 joints 2-3/8" N-80 EUE tailpipe with a 1.81" F-nipple one joint off bottom.
 b) 2-3/8" X 5-1/2" Uni VI packer with a 1.875" F-profile in on/off tool above packer. Set packer at 10320'. c) 2-3/8" N-80 EUE tubing to surface.

Flange up wellhead and flow well to pit. Swab as necessary. Supplemental brief will follow pending swab test.