

Submit to Appropriate
District Office
State Lease - 6 copies
Fee Lease - 5 copies

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-101
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OCT 13 '89

API NO. (assigned by OCD on New Wells)

30-015-2335100

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

LAKEY COM

8. Well No.

1

9. Pool name or Wildcat

North Loving (Bone Springs)

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work:

DRILL ☐

RE-ENTER ☐

DEEPEN ☐

PLUG BACK ☒

b. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER ☐

SINGLE
ZONE ☒

MULTIPLE
ZONE ☐

2. Name of Operator

Quinoco Petroleum, Inc.

3. Address of Operator

P. O. Box 378111, Denver, Colorado 80237

4. Well Location

Unit Letter L : 2280 Feet From The South Line and 660 Feet From The West Line

Section 20

Township 23S

Range 28E

NMPM

Eddy

County

10. Proposed Depth
+ 6420

11. Formation

12. Rotary or C.T.

13. Elevations (Show whether DF, RT, GR, etc.)

3076' RKB

14. Kind & Status Plug Bond

15. Drilling Contractor

16. Approx. Date Work will start

10/10/89

17.

Existing PROPOSED CASING AND CEMENT PROGRAM

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
20"	16"	65#	450'	750	Surf
14-3/4"	10-3/4"	40.5#	2415'	2175	
9-7/8"	7-5/8"	29.7#	9615'	1610	

APPROVAL VALID FOR 180 DAYS

PERMIT EXPIRES 5-1-90

UNLESS DRILLING UNDERWAY

Quinoco Petroleum, Inc. proposes to abandon the Atoka and Upper Morrow zones and recompleate to the bone Springs formation as follows:

1. MIRU pulling unit. Kill well with 10#/gal brine if necessary, ND tree, NU BOP's.
2. POOH w/2-3/8" tubing and packer.
3. RU wireline and set 5" CIBP @ $\pm 12,000$ ft. Dump 50' cement on top of bridge plug. RU and run CBL-GR log from 8,000/ft to $\pm 5,000$ ft. Correlate to Welx Acoustic Velocity Neutron Log. Squeeze if necessary.
4. Perforate Bone Springs @ 6405-6415 and 6356-6370 ft w/4" HSC guns with 2 shots per foot for a total of 48 - 0.50" holes.
5. TIH w/ 2-3/8" tubing, seating nipple and packer. Spot acid across perforations and pull packer above perforations and set at $\pm 6,300$ ft.

(continues on the back side)

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Holly S. Richardson TITLE Production Technician DATE 10/6/89

TYPE OR PRINT NAME Holly S. Richardson (303) TELEPHONE NO. 850-6322

(This space for State Use)

ORIGINAL SIGNED BY

MINERALS

SUPERVISOR, DISTRICT

OCT 30 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: Need to isolate Atoka + Morrow Perfs

6. Acidize w/ 3,000 gallon 7 1/2% NEFE acid with additives.
Drop ball sealers in acid.
7. Swab and flow test.
8. Frac if necessary per recommendations to follow w/ 50,000 gal of versagel HT 1400
& 94,000 # 20/40 sand down casing at 40 BPM.
9. Swab and flow test well. If well will not flow - P00H w/ tubing and Packer.
TIH w 2-3/8" tubing and set @ ±6500 ft.
10. If well is commercial and will not flow, run bottom hole pump and rods.
Set pumping unit.