

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C  
Revise

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

5a. Indicate Type of Lease  
State ☐ ☒ X  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Veraguth Com
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER 0 990 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 23-S RANGE 28-E NMPM.	10. Field and Pool, or Wildc Und. Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3065.8	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1103.

Propose to PxA per the following:

Load hole with 10# brine. Pull rods, pump and tubing. Go in hole with cast iron bridge plug and tubing and set plug at 3262 (50' above top perf.) Spot 25 sacks of class C neat cement (154' plug). Load hole with 25# of gelled brine. Pull up tubing to 2527' and spot 25 sacks of class C neat cement. (Top of Delaware.) Pull up tubing to 682 and spot 25 sacks of class C neat cement. (Surface casing shoe). Pull up and locate tubing at 62' and spot 10 sack surface plug. Cap and install PxA marker.

O+4-NMOCD, A 1-HOU 1-Stafford 1-McKay Oil

RECEIVED

AUG 19 1982

O. C. D.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Randolph TITLE Administrative Analyst DATE 8-17-82

APPROVED BY Mark Randolph TITLE OIL AND GAS INSPECTOR  
CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness  
Plugging

AUG 22 1982