

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.D.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103  
Revised 10-1-

DEC 8 1982

O. C. D.

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	LG-588	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company ✓	8. Farm or Lease Name State MF
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 24-S RANGE 27-E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat Delaware
11. Elevation (Show whether DF, RT, GR, etc.) 3208.9 GL	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to PXA well as follows:

Move in service unit. Displace hole with 10# gelled brine. Spot 100 sacks class C neat cement with 2% CACL per sack from 2250' to 1700' across 10-3/4" casing shoe at 2110'. WOC 4 hours. Tag plug. If plug is tagged above 2060' proceed. If below 2060' spot enough cement to raise TCMT to 2060'. Pull up and spot 10 sacks of class C neat cement from 55' to surface. Weld on cap and install PXA marker.

0+4-NMOCD,A 1-HOU 1-W. Stafford, HOU 1-DMF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Assist. Admin. Analyst DATE 12-6-82

APPROVED BY Mike Wilkins TITLE OIL AND GAS INSPECTOR DATE DEC 13 1982

CONDITIONS OF APPROVAL, IF ANY:

Notary Public in and for the State of New Mexico