ห ร	L A		O U R S	U A R T	FIELD TRIP REPORT								
P E C T I O	S S	IL			Name B. W. Weaver Date 5-5-85 Mi								
	I F I C A T I O N	I T Y		ER		ure 6:00 am	Tim	$= \frac{J}{J} $	Miles <u>137</u>	_District			
				н		-				_Car No	8632		
ы К				n U R S	In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.								
					Signature	BW Wear	euses visi	leu anu any ac	tion taken.	•			
			<u> </u>	3									
_	0	D	8							-			
P				2	<pre>Well E-35-24-26 Mesa Petr. Corp., Moore #2, P & A. Set retainer at 3341' and squeezed 75 Sx Class C in perfs at 4823' to 4827' at 700# PSI, 10 Sx on top of retainer.</pre>								
						Set 25 Sx 281							
,					Set 25 Sx 1930'-1830' Set 25 Sx 300'-200'								
						Jec 23 5x 300	-200	•					
			i										
:						•							
					•								
-						· .							
	-							•					
								2 [*] ·					
								· ··					
					Mileage		Per Diem		Hours				
					UIC RFA		UIC		UIC				
					.Other		Other		RFA Other	2			
											ĺ		
	PE JN PERFO	RMED				INSPECTION CLASSIFICATION			NATURE OF SPECIFIC WELL OR FACILITY INSPECTED				
Р С Т Я	- Rep	gging gging 1 Tes air/H	r Cle t forko	anup	resulting injection tests, sur	Roclamation Fund				j ion on j prođ. inj.			
н - ₩ -	- Wat - Mis - Wat - Oth	hap c er Cc	or Sp	ill inati	R = Inspection on O = Other - In Roclamatio					operations S = SWD U = Underground Storage G = General Operation F = Facility or location			
E = indicates some form of unforcement action taken in the M = Meetin field (show immediately below the letter U, R or O) O = Other										,			