

WELL LOCATION AND ACREAGE DEDICATION PLAT

Supersedes E-128
Effective 1-1-85

NOV 9 1982

All distances must be from the outer boundaries of the Section.

Operator Dinero Operating Co.		Lease Aminoil Fed		O. C. D.		Well No. 1
Well Letter J	Section 22	Township 24 South	Range 28 East	County ARTESIA, OFFICE		

Actual Footage Location of Well:

2030 feet from the South line and 1680 feet from the East line


Ground Level Elev. 2969.6'	Producing Formation MORROW	Pool Name MALAGA ATOKA MORROW	Dedicated Acreage: 320 Acres
-------------------------------	-------------------------------	----------------------------------	---------------------------------

1. Outline the acreage dedicated to the subject well by colored pencil or hatchure marks on the plat below.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☒ Yes ☐ No If answer is "yes," type of consolidation COMMUNITIZATION

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.)

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission.



CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Lavonda Norman

Name

Lavonda Norman

Position

Production Supervisor

Company

DINERO OPERATING COMPANY

Date

August 27, 1982

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed

August 28, 1982

Registered Professional Engineer
and/or Land Surveyor

Ronald J. Eidson

Certificate No. JOHN W. WEST 678
PATRICK A. ROMERO 6668
Ronald J. Eidson 3239

2/2/83

MCCLURE W/AM DINERO
APPROX SLIGHT LEAK @ TOP
OF 7 1/2" LINER

12-12-83

DINERO CRACK REPAIR
AMINOIL FED NO. 15 22-24-28

COMPLETED IN MARCH. LEAK REPAIR WORK

Memo

From
LES CLEM
District Super

SPOT REPAIR TOP OF ~~CRACK~~ LINER

ONLY FINDER UP FOR ~~REPAIR~~

TABLET REPAIR ~~MINOR~~ - OK

WORK NOT TO PROCEED AT TOP

CRACK REPAIR WILL BE COMPLETED

REPAIR WORK

To Mr. Stagner
Re:

Dinero Operating Co.

Aminoil Federal # 1-5-22-24-28

TX application

Top of liner apparently has a
small seep - could get a
small bubble and a pressure
build up 3-400 # in 18-20
hrs. as info on attached sketch
shows it looks well protected
I think it will be OK to
go ahead on the TX.

Les.