	•		DICE		
Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		+ orm C-103 Revised 1-1-80		
OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088		8	WELL API NO. 30-015-24922		
DISTRICT II P.O. Drawer DD, Anesia, NM 88210 Santa Fe, New Mexico 87504 2008		87504-2088	5. Indicate Type of Lease STATE FEE X		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	MAY 2559904 '90		6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN ON PLUS PACK INSE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITSIA" OFFICE (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
1. Type of Well: OL OAS WELL XX	OTHER		Craft 25 Com		
2. Name of Operator		8. Well No.			
Quinoco Petroleum, Inc.					
3. Address of Operator		9. Pool name or Wildcat			
P.O. Box 378111, Denver, CO 80237		Salt Draw Atoka			
4. Well Location Unit Letter					
Section 25 Township 24S Range 28E NMI'M Eddy County					
10. Elevation (Show whether DF, RKB, RI, GR, etc.) 2,917 ' GL					
11. Check A	Appropriate Box to Indicate N	Nature of Notice, Re	eport, or Other Data		
			SEQUENT REPORT OF		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT					
PULL OR ALTER CASING CASING TES			MENT JOB		
OTHER: Plug off current perfs & re-perf X OTHER: Atoka					

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Quinoco Petroleum, Inc. proposes to plug off the current Atoka perfs at 11,951-78', 12,032-37', 12,003-21' and re-perf the Atoka up-hole as follows:

- MIRU completion unit. Kill well w/10 ppg brine if necessary. ND tree. NU BOP's. TOH w/2-3/8" tbg & seal assembly.
- RIH w/WL & set CIBP @11,920'. Dump 50' of cmt on top of BP. Circhole clean. RU WL & run CBL-GR logs from 11,870' to 8,500'. Squeeze zone to be perforated if necessary.
 RIH w/4" Vann Gun Assembly; guns, F.H., 4' 2-3/8" 8rd handling sub, 3 jts 2-3/8" 8rd.
- 3. RIH w/4" Vann Gun Assembly; guns, F.H., 4' 2-3/8" 8rd handling sub, 3 jts 2-3/8" 8rd. 2-3/8" MTR with 1.81 latch, 2-3/8" bar pressure vent, 1 jt 2-3/8", Guiberson Uni VI packer w/XL on-off tool with F nipple. Load 2000' of tbg w/10 lbs per gal brine to create 4,200 lbs underbalance. Continue GIII w/tbg strings. RU Schlumberger, RIH w/GR-CCL tool, log from TD to 11,300'. Place gun assembly on depth. Set pkr w/9 pts compression. RD BOP's, RU WH, stake flow lines. (Continued on back)

I hereby certify that the info	inflation above is true and complete to the best of my knowle Ily S. Richardson	ofge and belief. 	DAIE5/21/90
TYPE OR PRINT NAME	Holly S. Richardson	(303) 850-6322	ті ја коле ко.
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILLIAMS SUPERVISOR, DISTRICT I		MAY 2 9 1990
APPROVED BY		TITLE	

- Release drop tube to open bar pressure vent to test. 4.
- Drop etonating bar to perforate Atoka @ 11,775' to 11,784' v/4 SPF w/32 grams deep 5. penetrating charges. Flow well to pit to clean up.
- RD and release equipment. Flow well for 24-48 hours to clean up. 6.
- RU swab unit. RU SU. Pump 2500 gal 20% NEFE HCl w/60-1.3 sp. gr. balls. Drop 5 balls 7. between each 180 gal stage of acid. Flush w/50 bbl 2% KCl wtr.

٠,

Place well on production. 8.

Should the Atoka formation prove to be non-commercial, Quinoco Petroleum, Inc. proposes to plugback this well to the Bone Springs as follows:

- Kill well & RU completion unit. ND tree. NU BOP's. 1.
- Unset Guiberson UNI Packer VI and POOII w/2-3/8" tbg. Set CIBP w 35' Cap e 11,700 2.
- RU WL & set CIBP & 100' cmt plug @ 11,276-376' (Penn.). Circ hole clean. Set CIBP & 100' cmt plug @ 9,513-613' (Wolfcamp). 3.
- Correlate CBL-GR logs run w/open-hole logs. Squeeze zones to be perforated @ 3. 8,707-14' & 8,768-80' if necessary.
- Perforate the Bone Springs @ 3,707-14' & 8,768-80' (19 ft) u/4'' HCS guns u/2 shots 4. per foot for a total fo 39 0.50" holes.
- TIH w/2-3/8" tbg, seating nipple & 7" pkr. Spot acid across perforations & pull pkr 5.