

LIGHTFOOT COM #2
P, 660' FSL & 660' FEL
Sec. 14, T-24-S, R-28-E
Eddy County, New Mexico

Page 2

- 1/18/85 - TD 9820'. 24 Hrs. WOC. Repair BOP, test BOE to 10,000#, Hydrill to 5000#, ok. Wing valve on choke manifold will not hold. WO valves.
- 1/19/85 - TD 9820'. 24 Hrs. WOC. Install new valves in manifold, install new rams. Tested rams & choke manifold to 10,000#, ok.
- 1/20/85 - TD 9820'. MW 8.9#, 5 3/4 Hrs. PU DC & RIH. 5 1/2 Hrs. Drl cmt & DV tool. 1/2 Hr. Test csg to 1200#, ok. PU DP & RIH. Drl FS, FS & formation w/6 1/2" bit.