


STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501



Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
T-6-6449

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry	7. Unit Agreement Name
2. Name of Operator Exxon Corp.	8. Form or Lease Name New Mexico ER State
3. Address of Operator P. O. Box 1600, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER I, 2251 FEET FROM THE South LINE AND 666 FEET FROM THE East LINE, SECTION 36, TOWNSHIP 23S, RANGE 25E, NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR-3366, DF-3877, KB-3878	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

We propose to plug and abandon this well as follows:

Set plug at 3170 w/10 sx cmt.  
CIBP at 2586 w/35' cmt.  
Set plug at 1910 w/20 sx cmt.  
Set plug at 1650 w/35 sx cmt.  
Set plug at 1338 w/30 sx cmt.  
Set plug at 482 w/30 sx cmt.  
Set plug 50'-surface w/15 sx cmt.  
Cut off wellhead & install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Melba Knippling TITLE Unit Head DATE 8/12/85  
APPROVED BY \_\_\_\_\_ TITLE Original Signed By  
Les A. Clements DATE SEP 03 1985  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ Supervisor District II